

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007238/T1TCN2**Date:** 23/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCNW00128262004

Claimant Vehicle No : SLV5173T **Insured Vehicle No :** SKL3135G

Date of Loss: 25/06/2021 Nature of Claim: TP Claim No: SNM21D203570/C01/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV5173T**

Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: HRA2549086A

Reg. Date: 29/12/2017 (Man. Year: 2017) Chassis No: SJNFEAJ11U2153065

Colour: Grey Odometer: 73157 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,194.57	13,617.84	2,576.73	15.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	1,430.00	740.00	34.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,364.57	15,047.84	3,316.73	18.06
+ GST 7.00/7.00% (\$\$)	1,285.52	1,053.35	232.17	18.06
Nett Amount (\$\$)	19,650.09	16,101.19	3,548.90	18.06

INSPECTION

Date of Assignment: 01/07/2021

Date Inspected: 05/07/2021 Inspected At: Ethoz Automotive Solutions Ltd (HQ)
30, BUKIT BATOK CRESCENT
Singapore 658075

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2021)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV5173T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	682.90 FN	*682.90 FN
2	1		*FRONT BUMPER LOWER GARNISH	Cut	195.20 FN	*195.20 FN
3	10		*FRONT BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
4	1		*FRONT BUMPER REINFORCEMENT	Bent	831.50 FN	*831.50 FN
5	1		*FRONT BUMPER BEAM	Not Necessary	415.70 FN	*- FN
6	1		*FRONT BUMPER SPONGE	Cracked	219.50 FN	*219.50 FN
7	2		*FRONT BUMPER REINFORCEMENT BRACKET	Bent	387.40 FN	*387.40 FN
8	2		*FRONT BUMPER LOWER ABSORBER	Not Necessary	219.00 FN	*- FN
9	1		*FRONT BUMPER RETAINER RH	Necessary	25.40 FN	*25.40 FN
10	1		*FRONT GRILLE	Cracked	486.00 FN	*486.00 FN
11	10		*FRONT GRILLE CLIPS	Necessary	80.00 FN	*80.00 FN
12	1		*FRONT GRILLE LOGO	Necessary	125.40 FN	*125.40 FN
13	1		*HEADLAMP RH	Cracked	3,243.00 FN	*3,243.00 FN
14	1		*BONNET	Bent	1,134.50 FN	*1,134.50 FN
15	10		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FN	*- FN
16	2		*BONNET HINGE RH/LH	Bent	130.00 FN	*130.00 FN
17	1		*BONNET LOCK	Not Necessary	70.00 FN	*- FN
18	1		*FRONT FENDER RH	Repair	753.50 FN	*- FN
19	1		*FRONT FENDER INNERSHIELD RH	Deformed	128.30 FN	*128.30 FN
20	10		*FRONT FENDER SHIELD CLIPS	Necessary	50.00 FN	*50.00 FN
21	1		*FRONT FENDER WHEELARC GARNISH RH	Deformed	540.50 FN	*540.50 FN
22	1		*FRONT BUMPER SIDE GARNISH RH	Cut	125.50 FN	*125.50 FN
23	1		*FRONT FOGLAMP RH	Not Necessary	301.00 FN	*- FN
24	1		*HEADLAMP TOP PANEL RH	Repair	83.90 FN	*- FN
25	1		*SUPPORT TOP PANEL	Repair	588.10 FN	*- FN
26	1		*SUPPORT LOWER PANEL	Repair	110.00 FN	*- FN
27	1		*WIPER WASHER TANK	Not Necessary	188.50 FN	*- FN
28	1		*FRONT AIRGUIDE RH	Deformed	90.20 FN	*90.20 FN
29	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
30	1		*COOLANT	Not Necessary	30.00 FS	*- FS
31	1		*HEADLAMP LH	Cracked	3,243.00 FN	*3,243.00 FN
32	1		*HEADLAMP LOWER BRACKET RH	Deformed	255.00 FN	*255.00 FN
33	1		*AIRCON CONDENSER	Bent	420.00 FN	*420.00 FN
34	1		*TURBO INTERCOOLER	Bent	1,170.00 FN	*1,170.00 FN
35	1		*RADIATOR TOP COVER	Deformed	95.00 FN	*95.00 FN
36	1		*RADIATOR LOWER AIRGUIDE	Deformed	156.00 FN	*156.00 FN
37	1		*AIRCON COOLING PIPE	Bent	204.75 FN	*204.75 FN
38	1		*AUTO OIL COOLER	Bent	645.00 FN	*645.00 FN
39	1		*ENGINE LOWER COVER	Deformed	378.00 FN	*378.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	17,986.75	15,127.05
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,792.18	1,509.21
Total Parts (S\$)	16,194.57	13,617.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,000.00	600.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	700.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	30.00
4	TO TOP UP AIR CON GAS	New	120.00	100.00
Gross Labour Cost (\$\$)			2,170.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >