

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III21007240/T1TF3N2**Date:** 08/10/2021**REFERENCE**

Insured/Claimant: PAN PACIFIC VAN &amp; TRUCK LEASING PTE LTD

Policy No: D19MFL0005549\_01

Date of Loss: 28/06/2021

Nature of Claim: OD

Claim No: MFL2021D0002823

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBJ2664U**

Make &amp; Model: NISSAN NV350, 2.5 (A)

Engine No: YD25042274B

Reg. Date: 28/02/2019 (Man. Year: 2018)

Chassis No: JN1MC2E26Z0030845

Colour: Blue

Odometer: 85510 km

Engine Capacity: 2488 cc

Market Value/New Car Price: S\$66,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15

Rear Tyre Size: 195R15

Front Left Side: Triangle 6 mm

Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm

Rear Right Side: Triangle 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,987.00	5,253.00	8,734.00	62.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,495.00	1,810.00	1,685.00	48.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,482.00</b>	<b>7,063.00</b>	<b>10,419.00</b>	<b>59.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
<b>- Excess (S\$)</b>	1,500.00	1,500.00	0.00	0.00
<b>(S\$)</b>	15,982.00	4,000.00	11,982.00	74.97
<b>+ GST 7.00/7.00% (S\$)</b>	1,118.74	280.00	838.74	74.97
<b>Nett Amount (S\$)</b>	<b>17,100.74</b>	<b>4,280.00</b>	<b>12,820.74</b>	<b>74.97</b>

**INSPECTION**

Date of Assignment: 01/07/2021

Date Inspected: 01/07/2021 Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)  
56 Loyang Way #06-07, Loyang Enterprise  
Building  
Singapore 508775

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 08 Oct 2021)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ2664U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (WCP)	Cracked	280.00 F	*280.00 F
2	1	*FRONT BUMPER SIDE RETAINER LH/RH (WCP)	O/s Deformed/N/s Not Necessary	150.00 F	*75.00 F
3	2	*FRONT FOG LAMP GARNISH LH/RH (WCP)	Not Necessary	130.00 F	*- F
4	1	*FRONT BUMPER CENTRE GRILLE (WCP)	Cracked	380.00 F	*380.00 F
5	1	*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	350.00 F	*- F
6	1	*FRONT BUMPER CENTRE BEAM (WCP)	Bent	95.00 F	*95.00 F
7	1	*FRONT BUMPER STAY LH/RH (WCP)	O/s Bent/N/s Not Necessary	100.00 F	*50.00 F
8	1	*TOWING COVER (WCP)	Not Necessary	20.00 F	*- F
9	1	*FRONT PANEL (WCP)	Bent	650.00 F	*650.00 F
10	1	*FRONT PANEL LOWER CENTER (WCP)	Bent	75.00 F	*75.00 F
11	1	*FRONT PANEL LOWER LH/RH (WCP)	O/s Bent/N/s Not Necessary	310.00 F	*155.00 F
12	1	*FRONT GRILLE (WCP)	Cracked	350.00 F	*350.00 F
13	1	*FRONT GRILLE LOGO (WCP)	Necessary	55.00 F	*55.00 F
14	1	*HEADLAMP LH/RH (WCP)	O/s Cracked/N/s Not Necessary	500.00 F	*250.00 F
15	1	*WIPER PANEL COVER (WCP)	Not Necessary	120.00 F	*- F
16	1	*WIPER MOTOR (WCP)	Not Necessary	165.00 F	*- F
17	1	*WIPER LINK ASSY (WCP)	Not Necessary	220.00 F	*- F
18	1	*INTERCOOLER (WCP)	Not Necessary	1,600.00 F	*- F
19	1	*INTERCOOLER GARNISH (WCP)	Not Necessary	135.00 F	*- F
20	1	*OIL COOLER (WCP)	Not Necessary	580.00 F	*- F
21	1	*OIL COOLER GARNISH (WCP)	Not Necessary	135.00 F	*- F
22	1	*AIRCON LIQUID PIPE (WCP)	Not Necessary	320.00 F	*- F
23	2	*STEP GARNISH LH/RH (WCP)	Not Necessary	190.00 F	*- F
24	1	*BLOWER MOTOR ASSEMBLY (WCP)	Not Necessary	600.00 F	*- F
25	1	*AIRCONDITIONING/HEATER ASSY (WCP)	Cracked	1,800.00 F	*1,800.00 F
26	1	*HORN (WCP)	Bent	50.00 F	*50.00 F
27	1	*AIR GUIDE LOWER (WCP)	Not Necessary	50.00 F	*- F
28	1	*RADIATOR (WCP)	Not Necessary	650.00 F	*- F
29	1	*RADIATOR FAN BLADE (WCP)	Not Necessary	150.00 F	*- F
30	1	*CORNER PANEL LH/RH (WCP)	O/s Bent/N/s Not Necessary	390.00 F	*195.00 F
31	1	*PARKING BRAKE CONTROL (WCP)	Bent	220.00 F	*220.00 F
32	2	*DASHBOARD LOWER CENTRE (WCP)	Not Necessary	400.00 F	*- F
33	1	*DASHBOARD LOWER DRIVER SIDE (WCP)	Not Necessary	150.00 F	*- F
34	1	*DASHBOARD REINFORCEMENT (WCP)	Not Necessary	400.00 F	*- F
35	1	*DASHBOARD ASSEMBLY (WCP)	Not Necessary	650.00 F	*- F
36	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
37	1	*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
38	2	*FRONT DOOR CO REG STICKER	Necessary	50.00 FS	*25.00 FS
39	1	*FRONT NUMBER PLATE	Bent	45.00 FS	*30.00 FS
40	1	*RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
41	1	*TRANSMISSION FLUID	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Sub Total (\$\$) 12,745.00 4,785.00**  
**+ Margin on L,N Items 10.00/10.00% (\$\$) 1,242.00 468.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
<b>Total Parts (\$)</b>						<b>13,987.00</b>	<b>5,253.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CUT/WELD DAMAGED PANELS,STRAIGHTEN & PANEL BEAT CHASSIS FRAME & OTHER PANELS,ALIGN DOORS,TO REMOVE & REPLACE DAMAGED PARTS	New	1,500.00	800.00
2	TO SPRAY PAINTING FRONT & LH/RH SIDE PORTIONS	New	1,200.00	800.00
3	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS	New	150.00	30.00
4	TO CHECK AND RECTIFY LIGHTING,WIRING AND ALL ELECTRICAL COMPONENTS	New	150.00	30.00
5	TO REMOVE & REFIT RADIATOR,FAN BLADE,OTHER COMPONENTS & TOP UP A/C GAS	New	150.00	0.00
6	TO REMOVE & REFIT DASHBOARD,BLOWER,EVAPORATOR & OTHER COMPONENTS	New	250.00	100.00
7	TOWING FEE	New	95.00	50.00
<b>Gross Labour Cost (\$)</b>			<b>3,495.00</b>	<b>1,810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >