

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007241/KPA3Q2**Date:** 30/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070010052
Claimant Vehicle No :	SMH3236X	Insured Vehicle No :	SMS660R
Date of Loss:	30/06/2021	Nature of Claim:	TP
		Claim No:	1789632380SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH3236X		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	LEB7102236
Reg. Date:	18/01/2019 (Man. Year: 2018)	Chassis No:	GP72001611
Colour:	Metallic Pearl White	Odometer:	228753 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	KAPSEN 7 mm	Rear Left Side:	KAPSEN 7 mm
Front Right Side:	KAPSEN 7 mm	Rear Right Side:	KAPSEN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,404.04	1,448.04	4,956.00	77.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	420.00	1,900.00	81.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,724.04	1,868.04	6,856.00	78.59
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	8,724.04	1,500.00	7,224.04	82.81
+ GST 7.00/7.00% (S\$)	610.68	105.00	505.68	82.81
Nett Amount (S\$)	9,334.72	1,605.00	7,729.72	82.81
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,732.45		
Global Sum Settlement (S\$)		1,500.00		

INSPECTION

Date of Assignment:	01/07/2021	
Date Inspected:	02/07/2021	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (BENT)	1st Accident	1,193.70 FL	*- FL
2	1		*REAR TAILGATE H LOGO (NECESSARY)	1st Accident	32.30 FL	*- FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM (NECESSARY)	1st Accident	55.00 FL	*- FL
4	1		*REAR TAILGATE HYBRID EMBLEM (NECESSARY)	1st Accident	78.90 FL	*- FL
5	1		*REAR TAILGATE CHROME	Serviceable	383.10 FL	*- FL
6	1		*REAR TAILGATE LH REFLECTOR	Cut	340.80 FL	*340.80 FL
7	2		*REAR TAILGATE HINGE	Repair	131.00 FL	*- FL
8	10		*REAR TAILGATE SPOILER CLIP	Not Necessary	50.00 FL	*- FL
9	1		*SET REAR TAILGATE WINDSCREEN MOULDING (NOT NECESSARY)	1st Accident	195.00 FL	*- FL
10	1		*REAR TAILGATE INNER LOCK (REPAIR)	1st Accident	189.40 FL	*- FL
11	1		*REAR TAILGATE INNER RUBBER	Serviceable	168.50 FL	*- FL
12	1		*REAR TAILGATE INNER GARNISH (CRACKED)	1st Accident	320.00 FL	*- FL
13	1		*REAR LH TAILLAMP	Cut	520.50 FL	*520.50 FL
14	2		*REAR TAILLAMP LOWER BRACKET	Serviceable	179.00 FL	*- FL
15	1		*REAR BUMPER (DEFORMED)	1st Accident	1,150.60 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	53.00 FL	*- FL
17	1		*REAR BUMPER LH REFECTOR	Serviceable	65.00 FL	*- FL
18	1		*REAR BUMPER LH REFECTOR GARNISH	Serviceable	85.00 FL	*- FL
19	1		*REAR BUMPER LH REFECTOR INNER SPONGE	Serviceable	75.00 FL	*- FL
20	1		*REAR END PANEL	Repair	601.50 FL	*- FL
21	1		*REAR END PANEL OUTER SENSOR	Serviceable	90.50 FL	*- FL
22	1		*REAR END PANEL INNER GARNISH	Mtg Cracked	195.55 FL	*195.55 FL
23	1		*REAR END PANEL LH SIDE PANEL	Repair	385.50 FL	*- FL
24	1		*REAR FLOOR PANEL GARNISH BOX	Cracked	295.20 FL	*295.20 FL
25	1		*REAR FENDER LH INNER GARNISH	Mtg Cracked	658.50 FL	*458.00 FL
26	1		*SET REAR PARKING SENSOR (SHORTED)	1st Accident	280.00 FS	*- FS
27	1		*SET REAR NUMBER PLATE & CASING	Serviceable	50.00 FS	*- FS
28	1		*SEALANT	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					7,902.55	1,810.05
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,498.51	362.01
Total Parts (\$\$)					6,404.04	1,448.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
2	WIRING	New	100.00	20.00
3	TUFFKOTE	New	100.00	0.00
4	SPRAY PAINTING	New	1,000.00	200.00
5	LABOUR CHARGES	New	1,000.00	200.00
Gross Labour Cost (\$)			2,320.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >