

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007242/UPA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700023093
Claimant Vehicle No :	FBJ9670E	Insured Vehicle No :	SLN9973S
Date of Loss:	17/06/2021	Nature of Claim:	TP
		Claim No:	9700610493SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ9670E		
Make & Model:	KTM 200 DUKE, 200cc	Engine No:	0490658203
Reg. Date:	14/01/2015 (Man. Year: 2014)	Chassis No:	VBKJUC403EC027640
Colour:	Orange	Odometer:	0 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	668.00	668.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	240.00	240.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	908.00	908.00	0.00	0.00

INSPECTION

Date of Assignment:	01/07/2021	
Date Inspected:	02/07/2021	Inspected At: KATOOM CUSTOMS (HQ) 8 KAKI BUKIT AVE 4, #05-55 PREMIER @ KB, SINGAPORE 415875.
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ASSLY PILLION FOOT PEG RH	Cut	15.00 F	*15.00 F
2	1		*FOOTREST FRONT L/S CPL	Cut	15.00 F	*15.00 F
3	2		*INDICATOR ASSLY LH	Cracked	70.00 F	*70.00 F
4	2		*INDICATOR ASSLY RH	Cracked	70.00 F	*70.00 F
5	1		*COVER FUEL TANK R/S BLACK MAT	Cut	35.00 F	*35.00 F
6	1		*COVER FUEL TANK L/S BLACK MAT	Cut	35.00 F	*35.00 F
7	1		*TANK COVER TOP+DECALS -ELEC ORANGE	Necessary	120.00 F	*120.00 F
8	1		*MASK SPOILER R/S E ORANGE	Damaged	28.00 F	*28.00 F
9	1		*ASSLY PILLION FOOT REG RH	Cut	15.00 F	*15.00 F
10	1		*FOOTREST FRONT L/S CPL	Missing	15.00 F	*15.00 F
11	1		*FOOTREST BRACKET FRONT L/S (HOLDER STEP LH)	Broken	35.00 F	*35.00 F
12	1		*FOOTREST BRACKET REAR R/S	Bent	30.00 F	*30.00 F
13	1		*CHARGE LEVER (SILVER)	Cut	32.00 F	*32.00 F
14	1		*FOOT BRAKE LEVER	Scratched	32.00 F	*32.00 F
15	1		*TENSION ROD COMPLETE	Damaged	18.00 F	*18.00 F
16	1		*BRAKE LEVER FRONT	Scratched	18.00 F	*18.00 F
17	1		*MIRROR LHS	Cut	20.00 F	*20.00 F
18	1		*KTM-D-EO-FIL-AMSOLL-P-10W40	Necessary	65.00 F	*65.00 F
F=Franchise part.						
					Total Parts (\$\$)	668.00 668.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT BIKE TOW	New	40.00	40.00
2	LABOUR	New	200.00	200.00
Gross Labour Cost (S\$)			240.00	240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >