

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Billy Tan

Date: 11 Aug 2021

**Preliminary Advice**

Vehicle No	: SJK3387M	Accident Date	: 25/06/2021
Make	: TOYOTA HIACE	Policy No.	: DMCVSNA00003052101
Assignment Date	: 01/07/2021	Excess	: S\$1,000.00
Date of Inspection	: 02/07/2021	Est. Duration of Repair	: 24
Inspection At	: AUTO SOON PTE LTD (HQ) BLOCK 176 SIN MING DRIVE, #01-10 SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,102.84	(ESTIMATE \$37,484.52 + SUPPLEMENTARY \$17,618.32)
Revised Amount	:S\$	32,078.07	
Check Items (Estimated)	:S\$	20,629.94	
Total	:S\$	52,708.01	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$		
Pre-Accident Value	:S\$	45,000.00	
COE / PARF Rebate	:S\$	0.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	45,000.00	

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$30,800 ON LUMP SUM BASIS.  
KINDLY APPROVE ON SUPPLEMENTARY.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.