9/13/21, 2:08 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG21007249/KPS3Q2

Date:

13/09/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070160024

Claimant Vehicle No :

SHD5336H 29/06/2021 Insured Vehicle No:

Nature of Claim:

SFV1900J TP

Claim No:

2409921526SG

JTDKB3FU503077251

2ZR2B79475

313133 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD5336H

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Reg. Date: 04/12/2018 (Man. Year: 2018)

Colour: Metallic Pearl White/Red

Engine Capacity: 1798 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Foo

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

Yes No

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 195/65 R15 Sailun 9 mm Sailun 9 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 195/65 R15 Sailun 9 mm

Sailun 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------|------------|------------|------------|--------|
| Parts | | 6,105.02 | 3,316.77 | 2,788.25 | 45.67 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 4,380.00 | 760.00 | 3,620.00 | 82.65 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Gross Total (S\$) | 10,485.02 | 4,076.77 | 6,408.25 | 61.12 |
| | + GST 7.00/7.00% (S\$) | 733.95 | 285.37 | 448.58 | 61.12 |

Nett Amount (S\$) 11,218.97 4,362.14 6,856.83 61.12

0.00

Global Sum Settlement (S\$)

INSPECTION

Date of Assignment: 30/06/2021

Trans-cab Auto Services Pte Ltd (Ang Mo Kio) Date Inspected: Inspected At: 30/06/2021

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

| No. Qty Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|---------------------------------------|--|-------------|--------------|
| 1 1 | *COVER ,FRONT BUMPER | Cracked | 516.00 FL | *516.00 FL |
| 2 1 | *GRILLE SUB-ASSY ,RADIATOR | Serviceable | 346.00 FL | *- FL |
| 3 1 | *GRILLE ,RADIATOR ,LOWER NO.1 | Serviceable | 170.10 FL | *- FL |
| 4 1 | *COVER ,ENGINE UNDER NO.2 | Serviceable | 38.20 FL | *- FL |
| 5 1 | *REINFORCEMENT SUB-ASSY ,FRONT BUMPER | Repair | 716.60 FL | *- FL |
| 3 1 | *ABSORBER ,FRONT BUMPER ENERGY | Cracked | 79.60 FL | *79.60 FL |
| 7 1 | *RETAINER ,REAR BUMPER SIDE ,LH | Distorted | 116.50 FL | *116.50 FL |
| 3 1 | *BRACKET ,FRONT BUMPER SIDE ,LH | Serviceable | 59.30 FL | *- FL |
| 9 1 | *UNIT ASSY ,HEADLAMP ,LH | Cracked | 2,637.60 FL | *2,637.60 FL |
| 10 1 | *COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1 | Serviceable | 960.50 FL | *- FL |
| 11 1 | *LAMP ASSY ,FOG ,LH | Mtg Broken | 951.40 FL | *951.40 FL |
| 12 1 | *FENDER SUB-ASSY ,FRONT LH | Repair | 977.80 FL | *- FL |
| 13 1 | *FRONT FENDER EMBLEM LH | Necessary | 54.60 FL | *54.60 FL |
| 14 1 | *LINER ,FRONT FENDER ,LH | Serviceable | 202.50 FL | *- FL |
| 15 1 | *FRONT FENDER CLIP | Not Necessary | 70.00 FS | *- FS |
| 16 1 | *SET FRONT FENDER LINER CLIP | Not Necessary | 75.00 FS | *- FS |
| 17 1 | *SET FRONT BUMPER CLIP | Necessary | 90.00 FS | *50.00 FS |
| F=Franchise part. S=SpcNett. | L=ListItemDisc. | | | |
| | | Sub Total (S\$) | 8,061.70 | 4,405.70 |
| | | - List Item Discount on L Items 25.00/25.00% (S\$) | 1,956.68 | 1,088.93 |
| | | Total Parts (S\$) | 6,105.02 | 3,316.77 |

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

9/13/21, 2:08 PM

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|-------------------------|------------|--------|
| Lab | our Items | | | |
| 1 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PAI, ADJUST AND REALIGN THE SAME | RTS New | 1,600.00 | 300.00 |
| 2 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 3 | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS | New | 240.00 | 0.00 |
| 4 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 5 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 1,600.00 | 440.00 |
| 6 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 7 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 20.00 |
| | | Gross Labour Cost (S\$) | 4,380.00 | 760.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >