

SCL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Kasyful Adzim Bin Mohamad Foaad
C/o: GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Date : 17 June 2021
Our ref : GPM/04/2103/TP

Accident Date : 10 April 2021
Inspection Date : 15 April 2021
Repairer Name : GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FBE 6396 T
Make / Model : Yamaha RXZ
Chassis No : PMY5PV100A0032113
Engine No : 5PV032113

Year / Capacity : 2010 / 133 cc
Colour : Red
Mileage : 37925

CONDITION OF TYRES

	Make	Size	Thrcad Balance	Rim
Front	Dunlop	2.50 -18	5 mm	Normal
Rear	Dunlop	2.50 -18	5 mm	Normal

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear and n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 102 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$7,500.00** on a contractual basis.

Under normal circumstances, the repair period would be about 20 (Twenty) working days.

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	N/s fork tube assy X SVC	Damage	\$ 680.00	\$ 680.00 X
1	Fairing cover (1 set) ✓	Damage	\$ 1,550.00	\$ 1,550.00 300
1	N/s handle bar ✓	Damage	\$ 115.00	\$ 115.00 90
1	Hand grip (1 set) X SVC	Damage	\$ 65.00	\$ 65.00 X
1	N/s handle bar end ✓	Damage	\$ 32.00	\$ 32.00 18
1	Clutch lever ✓	Damage	\$ 38.00	\$ 38.00 ✓
1	Meter assy SVC	Intact	\$ 750.00	
1	Fuel tank ✓	Damage	\$ 950.00	\$ 950.00 400
1	Front n/s footrest ✓	Damage	\$ 85.00	\$ 85.00 ✓
1	Front n/s footrest bracket X SVC	Damage	\$ 115.00	\$ 115.00 X
2	Rear absorbers ✓	Damage	\$ 570.00	\$ 570.00 240
1	Gear panel X SVC	Damage	\$ 55.00	\$ 55.00 X
1	Rear n/s footrest ✓	Damage	\$ 28.00	\$ 28.00 ✓
1	Exhaust pipe assy ✓	Damage	\$ 1,350.00	\$ 1,350.00 550
1	Exhaust protector X SVC	Damage	\$ 65.00	\$ 65.00 X
1	Rim assy (1 set) ✓	Damage	\$ 1,500.00	\$ 1,500.00 400
1	Rear rm hub X SVC	Damage	\$ 220.00	\$ 220.00 X
1	Swing arm X SVC	Damage	\$ 850.00	\$ 850.00 X
1	Swing arm shaft ✓	Necessary	\$ 55.00	\$ 55.00 38
1	Rear mudguard ✓	Damage	\$ 95.00	\$ 95.00 68
1	Rear passenger handle ✓	Damage	\$ 78.00	\$ 78.00 ✓
1	Rear taillamp ✓	Damage	\$ 110.00	\$ 110.00 95
1	Rear fender ✓	Damage	\$ 115.00	\$ 115.00 60
1	Seat ✓	Damage	\$ 285.00	\$ 285.00 180
			\$ 9,756.00	\$ 9,006.00 2668
			<i>Less 10%</i> \$ 975.60	<i>\$ 900.60</i>
Total Cost - List Items			\$ 8,780.40	\$ 8,105.40 2401.2

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
List Items Total c/f			\$ 8,780.40	\$ 8,105.40

SPECIAL NETT ITEMS

1	Number plate (1 set) ✓	Damage	\$ 28.00	\$ 28.00 ✓
1	Fork oil X SVC	Necessary	\$ 15.00	\$ 15.00
1	Fork oil seal X SVC	Necessary	\$ 28.00	\$ 28.00
1	Steering cone (1 set) X SVC	Necessary	\$ 75.00	\$ 75.00
1	Swing arm bush ✓	Necessary	\$ 75.00	\$ 75.00 ✓
1	Sticker (1 set) ✓	Necessary	\$ 95.00	\$ 95.00 ✓
1	Rear tyre (Depreciation) X SVC	Damage	\$ 300.00	\$ 150.00
Total Cost - Special Nett items			\$ 616.00	\$ 466.00 198

Total cost of parts

\$ 9,396.40 \$ 8,571.40

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 9,396.40	\$ 8,571.40

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00 ✓
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00 ✗
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00 200
4	To check , repair and straighten body frame to the original position.	\$ 350.00	\$ 350.00 200

GRAND TOTAL

\$ 10,356.40	\$ 9,421.40
--------------	-------------

3049.2

-20%: 2400

4 Days



C L APPRAISER PTE LTD

Vehicle Registration No.: FBE 6396 T

Our Ref No.: GPM/04/2103/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,500.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K.H
Automotive Appraiser