

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21005038/Gqce2	
	8 SHENTON WAY AXA TOWERSING			Date:	30/04/2021	
	ATTN: YU DOMINI	C YISHAN		Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 7116M	Veh. Inspected		FBE 6396T	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M037QY	Excess (\$)		0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date		22/04/2021	
2.	. Vehicle Particulars & Condition					
	Make & Model	YAMAHA RXZ	c.c		133	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	PMY5PV100A0032113	Colour		RED	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	2.50-18	DUNLOP		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	2.50-18	DUNLOP		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.					
5.	. General Information					
	Accident Date	10/04/2021	Inspect Date /	Time	22/04/2021 ( 04:00 PM )	
	Survey held at	GP MOTORING PTE LTD	-			
	282 MACPHERSON ROAD SINGAPORE 348607					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21005038/Gqce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor