

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21007255/KPA3Q2
Date: 30/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070171018
Claimant Vehicle No :	SHB9755R	Insured Vehicle No :	GBE1888Z
Date of Loss:	28/06/2021	Nature of Claim:	TP
		Claim No:	5834825150SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9755R		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G75480
Reg. Date:	14/07/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU403091190
Colour:	Metallic Pearl White/Red	Odometer:	98297 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,890.18	1,127.83	7,762.35	87.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,610.00	1,240.00	8,370.00	87.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,500.18	2,367.83	16,132.35	87.20
+ GST 7.00/7.00% (S\$)	1,295.01	165.75	1,129.26	87.20

Nett Amount (S\$)	19,795.19	2,533.58	17,261.61	87.20
+ Loss of Use (5.5 x S\$50.00/day) (S\$)		275.00		
+ Car Rental (5.5 x S\$96.30/day) (S\$)		529.65		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,345.68		
Global Sum Settlement (S\$)		3,300.00		

INSPECTION

Date of Assignment: 01/07/2021

Date Inspected: 01/07/2021

Estimated Period of Repair: 5.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Cracked	485.61 FL	*485.61 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*COVER ,REAR BUMPER LOWER	Serviceable	22.00 FL	*- FL
4	1		*GUARD ,REAR BUMPER CENTER	Serviceable	374.50 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*REFLECTOR ASSY ,REFLEX ,LH	Serviceable	39.00 FL	*- FL
8	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Repair	1,294.90 FL	*- FL
9	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM ,LH	Serviceable	293.00 FL	*- FL
10	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Repair	87.10 FL	*- FL
11	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Repair	98.90 FL	*- FL
12	1		*TAPE ,BLACK OUT ,NO.1 REAR LH	Not Necessary	21.90 FL	*- FL
13	1		*TAPE ,BLACK OUT ,NO.2 REAR LH	Not Necessary	34.90 FL	*- FL
14	1		*TAPE ,BLACK OUT ,NO.3 REAR LH	Not Necessary	15.40 FL	*- FL
15	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,LH	Serviceable	926.00 FL	*- FL
16	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	Serviceable	206.70 FL	*- FL
17	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Serviceable	339.60 FL	*- FL
18	1		*LENS & BODY ,REAR COMBINATION LAMP ,NO.2 LH	Serviceable	261.00 FL	*- FL
19	1		*PANEL SUB-ASSY ,QUARTER ,LH	Bent	871.50 FL	*871.50 FL
20	1		*LINER ,REAR WHEEL HOUSE ,LH	Repair	139.80 FL	*- FL
21	1		*COVER ,FLOOR UNDER ,NO.1 (LH)	Serviceable	175.10 FL	*- FL
22	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
23	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
24	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*50.00 FS
26	1		*DOOR TRIM CLIP	Not Necessary	60.00 FS	*- FS
27	1		*DOOR STICKER TEL NO	Necessary	100.00 FS	*60.00 FS
28	1		*HUB CAP	Serviceable	211.50 FS	*- FS
29	1		*RIM	Serviceable	1,879.40 FS	*- FS
30	1		*TYRE	Serviceable	350.00 FS	*- FS
31	1		*REAR FENDER CLIP	Not Necessary	60.00 FS	*- FS
32	1		*REAR FENDER LINER CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,681.61	1,467.11
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,791.43	339.28

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	8,890.18
						1,127.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	100.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	600.00
3	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	480.00	0.00
6	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
7	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
18	TO LIFT-UP /OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
19	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND TEST VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			9,610.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >