

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN		Ref:	CS3/LPC21007257/Gqf3e2		
	300 BEACH ROAD SINGAPORE 1995		Date:	15/07/2021		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 9515C	Veh. Inspected	I	SFV 827U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VC00/024719	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		02/07/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI GRANDIS 2.4	c.c		2378	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	JMYLRNA4W8Z000861	Colour		BLACK	
	Odometer	220875 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 ZR17	CST		6 mm	
	L/H Front Tyre	215/55 ZR17	CST		6 mm	
	R/H Rear Tyre	215/55 ZR17	CST		6 mm	
	L/H Rear Tyre	215/55 ZR17	CST		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S BODY.				
5.	General Information					
	Accident Date	01/07/2021	Inspect Date /	Time	02/07/2021 (03:00 PM)	
	Survey held at	REVOL CARZ GARAGE PTE LTD				
		BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21007257/Gqf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser