

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

1,100.00

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2098E

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION)

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	WING MIRROR RH	CRACKED	1,390.10	1,390.10
1	WING MIRROR OUTER CVR RH	MISSING	141.90	141.90
	LESS 25% DISCOUNT		-383.00	-383.00
			1,149.00	1,149.00
	<u>LABOUR</u>			
	PANEL BEATING.		150.00	100.00
	SPRAYPAINT CHARGE.		150.00	80.00
	TOWING FEE.		60.00	60.00
			360.00	240.00
	GRAND TOTAL		1,509.00	1,389.00

Report Ref No. CS/SMR21007261/Uuf3n2

CHUA KANG SENG

**Licensed Appraiser**