

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Christina Wong

Date: 16 Jul 2021

Preliminary Advice

Insured	: SBR8383Z		
Vehicle No			
TP Vehicle No	: PC3955U	Accident Date	: 01/07/2021
Make	: TOYOTA HIACE	Assignment Date	: 02/07/2021
Date of Inspection	: 05/07/2021	Est. Duration of Repair	: 2
Inspection At	: JOO HAK KEE AUTO PTE LTD (HQ) BLK 3007 UBI ROAD 1, #01-406 SINGAPORE 408701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,094.95
Revised Amount	:S\$	2,562.38
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,562.38

Lump Sum Repair	:S\$	2,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - () Lump Sum repair
-
- () The above survey was conducted on a 'without prejudice' basis.