

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007271/GPA3Q2
Date: 07/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	FBQ2605D	Insured Vehicle No :	SKM1594Y
Date of Loss:	31/01/2021	Nature of Claim:	TP
		Claim No:	0874822733SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ2605D	Engine No:	KB21E1086146
Make & Model:	HONDA SUPRA GTR 150, 149cc	Chassis No:	MH1KB2111KK086037
Reg. Date:	27/08/2019 (Man. Year: 2018)	Odometer:	25577 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	90/80-17	Rear Tyre Size:	120/70-17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,525.70	947.90	1,577.80	62.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	310.00	480.00	60.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,315.70	1,257.90	2,057.80	62.06
Approved Total (Overridden) (S\$)		1,000.00		

Nett Amount (S\$)	3,315.70	1,000.00	2,315.70	69.84
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 02/07/2021

Date Inspected: 02/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

The Sincere Motor Repairing Pte Ltd (Shaw Road)
 20 Shaw Road #01-03, Ching Shine Industrial Building
 Singapore 367956

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP ASSY	Not Necessary	285.00 FL	*- FL
2	1		*SET BALANCER	Not Necessary	68.00 FL	*- FL
3	1		*FRONT COWLING (BLACK)	Not Necessary	72.00 FL	*- FL
4	1		*BRAKE LEVER	Cut	28.00 FL	*28.00 FL
5	1		*CLUTCH LEVER	Not Necessary	29.00 FL	*- FL
6	1		*HANDLE BAR RH COVER (RED)	Cracked	48.00 FL	*48.00 FL
7	1		*HANDLE BAR LH COVER (BLACK)	Cut	60.00 FL	*60.00 FL
8	1		*FRONT RH COVER (RED)	Cut	55.00 FL	*55.00 FL
9	1		*FRONT LH COVER (RED)	Cut	55.00 FL	*55.00 FL
10	1		*REAR RH COVER (RED)	Not Necessary	120.00 FL	*- FL
11	1		*FRONT SIGNAL ASSY (RH)	Not Necessary	68.00 FL	*- FL
12	1		*FRONT SIGNAL COVER (LH)	Not Necessary	27.00 FL	*- FL
13	1		*HANDLE BAR	Bent	115.00 FL	*115.00 FL
14	1		*SET MIRROR	Cut	50.00 FL	*50.00 FL
15	1		*FORK TOP BRIDGE	Not Necessary	155.00 FL	*- FL
16	1		*FRONT FENDER	Cut	105.00 FL	*105.00 FL
17	1		*SET DECAL COMPLETE	Cut	128.00 FL	*128.00 FL
18	2		*FRONT FORK ASSY	Repair	490.00 FL	*- FL
19	1		*STEERING STEM WITH BEARING	Not Necessary	195.00 FL	*- FL
20	1		*FOOT REST BAR	Bent	55.00 FL	*55.00 FL
21	1		*FOOT REST BAR BRACKET	Not Necessary	58.00 FL	*- FL
22	1		*SET FOOT REST BAR RUBBER	Cut	25.00 FL	*25.00 FL
23	1		*GEAR SHIFT PEDAL	Bent	52.00 FL	*52.00 FL
24	1		*REAR BRAKE PEDAL	Not Necessary	70.00 FL	*- FL
25	1		*REAR COVER	Not Necessary	85.00 FL	*- FL
26	1		*EXHAUST HEAT SHIELD	Cut	65.00 FL	*65.00 FL
27	1		*IU	Cracked	156.00 FS	*156.00 FS
28	1		*FRONT WHEEL AXLE	Not Necessary	28.00 FS	*- FS
29	1		*IU BRACKET	Broken	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,782.00	1,032.00
- List Item Discount on L Items 10.00/10.00% (\$)	256.30	84.10
Total Parts (\$)	2,525.70	947.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY AFFECTED AREA	New	350.00	0.00
2	TO DISMANTLE & ASSEMBLY PARTS FOR REPAIR	New	380.00	280.00
3	TOWING VEHICLE TO WORKSHOP	New	60.00	30.00
Gross Labour Cost (\$\$)			790.00	310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >