

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007284/KVCN2**Date:** 25/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00057272102
Claimant Vehicle No :	SJM6750S	Insured Vehicle No :	GBH4628Y
Date of Loss:	01/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D203696/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM6750S	Engine No:	3ZZ4834166
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106130150
Reg. Date:	13/01/2009 (Man. Year: 2008)	Odometer:	184757 km
Colour:	Metallic Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55ZR16	Rear Tyre Size:	205/55ZR16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,235.75	1,593.66	9,642.09	85.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	970.00	2,330.00	70.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,535.75	2,563.66	11,972.09	82.36
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	14,535.75	2,000.00	12,535.75	86.24
+ GST 7.00/7.00% (\$\$)	1,017.50	140.00	877.50	86.24
Nett Amount (\$\$)	15,553.25	2,140.00	13,413.25	86.24

INSPECTION

Date of Assignment:	29/07/2021	
Date Inspected:	05/07/2021	Inspected At: Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM6750S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S	Repair	729.00 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD O/S	Cracked	285.00 FL	*171.20 FL
3	1		*HEADLAMP O/S	Mtg Cracked	1,165.00 FL	*785.30 FL
4	1		*HEADLAMP LOWER BRACKET O/S	Repair	109.00 FL	*- FL
5	1		*FRONT BUMPER	Buckled/Cracked	769.00 FL	*465.10 FL
6	1		*FRONT BUMPER LOWER SPLASH COWLING	Serviceable	396.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER	O/s Distorted	168.00 FL	*84.00 FL
8	1		*FRONT BUMPER FOGLAMP O/S	Mtg Cracked	287.00 FL	*287.00 FL
9	1		*FRONT BUMPER FOGLAMP OUTER GARNISH O/S	Dented	76.00 FL	*76.00 FL
10	1		*FRONT BUMPER LOWER GRILLE	Serviceable	365.00 FL	*- FL
11	1		*RADIATOR GRILLE BRACKET	Repair	147.00 FL	*- FL
12	1		*FRONT SHOCK ABSORBER O/S	Serviceable	389.00 FL	*- FL
13	1		*FRONT SHOCK ABSORBER MOUNTING O/S	Serviceable	95.00 FL	*- FL
14	1		*FRONT LOWER ARM O/S	Serviceable	487.00 FL	*- FL
15	1		*FRONT WHEEL KNUCKLE O/S	Serviceable	398.00 FL	*- FL
16	1		*FRONT WHEEL KNUCKLE BEARING O/S	Not Necessary	185.00 FL	*- FL
17	1		*FRONT BUMPER REINFORCEMENT	Repair	377.00 FL	*- FL
18	1		*DRIVE SHAFT O/S	Repair	689.00 FL	*- FL
19	1		*AIR INTAKE HOSE	Serviceable	243.00 FL	*- FL
20	1		*COOLANT EXPANSION TANK	Dented	195.00 FL	*130.95 FL
21	1		*FRONT FENDER INNER TOP BRACKET O/S	Serviceable	218.00 FL	*- FL
22	1		*ANTI ROLL BAR	Serviceable	335.00 FL	*- FL
23	2		*ANTI ROLL BAR BRACKET	Serviceable	90.00 FL	*- FL
24	2		*ANTI ROLL BAR BRACKET BUSHING	Not Necessary	50.00 FL	*- FL
25	2		*ANTI ROLL BAR ENDLINK	Serviceable	310.00 FL	*- FL
26	1		*CROSS MEMBER	Serviceable	1,673.00 FL	*- FL
27	6		*CROSS MEMBER BUSHING	Serviceable	390.00 FL	*- FL
28	1		*STEERING RACK ASSY	Serviceable	1,556.00 FL	*- FL
29	2		*TIE ROD END	Serviceable	178.00 FL	*- FL
30	1		*BONNET	Repair	980.00 FL	*- FL
31	1		*BONNET LOCK	Repair	295.00 FL	*- FL
32	1		*FRONT BUMPER CLIPS (12 Pcs)	Necessary	66.00 FS	*50.00 FS
33	8		*FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	44.00 FS	*44.00 FS
34	8		*FRONT BUMPER LOWER SPLASH COWLING CLIPS	Not Necessary	44.00 FS	*- FS
35	1		*FRONT ALLOY RIM O/S	Serviceable	450.00 FS	*- FS
36	1		*FRONT TYRE O/S	Serviceable	280.00 FS	*- FS
37	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
38	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,643.00	2,093.55
- List Item Discount on L Items 25.00/25.00% (\$)	3,407.25	499.89
Total Parts (\$)	11,235.75	1,593.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,400.00	400.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	TO REMOVE AND REFIT N/S FRONT TYRE & RIMS.TO PERFORM TYRE BALANCING	New	50.00	0.00
4	TO REMOVE AND REFIT N/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	200.00	0.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	100.00	0.00
6	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,400.00	550.00
7	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			3,300.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >