

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007285/TTCE2**Date:** 04/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00076572100

Claimant Vehicle No : FBS3842T**Insured Vehicle No :** SMM2275M

Date of Loss: 07/05/2021

Nature of Claim: TP

Claim No: SNM21D203695/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBS3842T**

Make & Model: YAMAHA XSR155 MANUAL, 155cc

Engine No: G3J6E0294207

Reg. Date: 06/04/2021 (Man. Year: 2021)

Chassis No: MH3RG4760MK019015

Colour: Black

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17

Rear Tyre Size: 140/70 R17

Front Left Side: TRAIL WINNER 6 mm

Rear Left Side: TRAIL WINNER 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,885.50	320.85	4,564.65	93.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	120.00	1,350.00	91.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,355.50	440.85	5,914.65	93.06
Approved Total (Overridden) (\$\$)		350.00		
Nett Amount (\$\$)	6,355.50	350.00	6,005.50	94.49

INSPECTION

Date of Assignment: 04/07/2021

Date Inspected: 05/07/2021 Inspected At:

A S Phoon Pte Ltd (toh Guan) (HQ)
BLK 36 TOH GUAN ROAD EAST ENTERPRISE
HUB #01-35
Singapore 408701

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Apr 2022)	
Parts:	N/A	YAMAHA XSR155 MANUAL 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS3842T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Not Necessary	75.00 F	*- FL
2	1		*FRONT FENDER SIDE COVER	Not Necessary	28.00 F	*- FL
3	1		*FRONT WHEEL AXLE	Not Necessary	28.00 F	*- FL
4	1		*CAST WHEEL, FRONT	Not Necessary	320.00 F	*- FL
5	1		*HEADLIGHT ASSY	Not Necessary	285.00 F	*- FL
6	1		*COVER, HEADLIGHT	Not Necessary	48.00 F	*- FL
7	1		*STAY, HEADLIGHT 2 (SILVER)	Not Necessary	45.00 F	*- FL
8	1		*STAY, HEADLIGHT (BLACK)	Not Necessary	85.00 F	*- FL
9	1		*LEVER 1	Not Necessary	28.00 F	*- FL
10	1		*END, GRIP	Not Necessary	12.00 F	*- FL
11	1		*HANDLEBAR	Bent	85.00 F	*85.00 FL
12	2		*FRONT FORK ASSY RH & LH	Not Necessary	700.00 F	*- FL
13	1		*STEM STEERING	Not Necessary	175.00 F	*- FL
14	1		*SET CONE BEARING	Not Necessary	80.00 F	*- FL
15	1		*COVER, CRANKCASE 1	Dented	120.00 F	*120.00 FL
16	1		*GASKET, CRANKCASE 1	Necessary	8.50 F	*8.50 FL
17	1		*SHIFT PEDAL ASSY	Repair	85.00 F	*- FL
18	1		*STAND, SIDE	Not Necessary	35.00 F	*- FL
19	1		*FRONT FOOTREST BRACKET LH	Not Necessary	55.00 F	*- FL
20	1		*BOLT	Not Necessary	8.00 F	*- FL
21	1		*FOOTREST REAR 1	Not Necessary	48.00 F	*- FL
22	1		*DOUBLE SEAT ASSY	Not Necessary	285.00 F	*- FL
23	1		*TAILLIGHT ASSY	Not Necessary	120.00 F	*- FL
24	1		*REAR REFLECTOR ASSY	Not Necessary	15.00 F	*- FL
25	1		*REAR SIGNAL RH	Not Necessary	55.00 F	*- FL
26	1		*MUFFLER COMP 1	Not Necessary	450.00 F	*- FL
27	1		*PROTECTOR, MUFFER 1	Not Necessary	70.00 F	*- FL
28	1		*CAP	Not Necessary	48.00 F	*- FL
29	1		*BOLT, HEX.SOCKETBUTTON	Not Necessary	5.00 F	*- FL
30	1		*FOOTREST, REAR RH	Not Necessary	48.00 F	*- FL
31	1		*FRONT FOOTREST RH	Not Necessary	48.00 F	*- FL
32	1		*PEDAL, BRAKE	Not Necessary	85.00 F	*- FL
33	2		*SIDE MIRROR LH & RH	Cut	90.00 F	*90.00 FL
34	1		*THROTTLE CABLE ASSY	Not Necessary	75.00 F	*- FL
35	1		*HANDLEGRIP	Cut	35.00 F	*35.00 FL
36	1		*THROTTLE CABLE INNER TUBE	Not Necessary	25.00 F	*- FL
37	1		*CAP GRIP UPPER	Not Necessary	30.00 F	*- FL
38	1		*CAP GRIP UNDER	Not Necessary	30.00 F	*- FL
39	1		*MASTER CYLINDER ASSY	Not Necessary	255.00 F	*- FL
40	1		*BRAKE LEVER	Not Necessary	28.00 F	*- FL
41	1		*WEIGHT	Not Necessary	25.00 F	*- FL
42	2		*DAMPER LOCATING 1	Not Necessary	8.00 F	*- FL
43	2		*BOLT	Not Necessary	8.00 F	*- FL
44	1		*COVER SIDE 1	Not Necessary	145.00 F	*- FL
45	1		*COVER SIDE 2	Not Necessary	145.00 F	*- FL
46	2		*EMBLEM	Not Necessary	16.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*4T	Necessary	18.00 F	*18.00 FL
48	1		*HELMET	Not Necessary	120.00 F	*- FL
49	1		*SIDE BAG	Not Necessary	250.00 F	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					4,885.50	356.50
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	35.65
Total Parts (\$\$)					4,885.50	320.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REALIGNMENT FRONT FORK ASSY	New	250.00	0.00
2	WORKMANSHIP	New	450.00	120.00
3	TRANSPORT TP-IDAC-WORKSHOP	New	160.00	0.00
4	BODY CHASSIS REPAIR	New	450.00	0.00
5	TRANSPORT 02 WAY TO REPAIR CHASSIS	New	160.00	0.00
Gross Labour Cost (\$)			1,470.00	120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >