

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007286/UGS3Q2
Date: 18/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKX1520C	Insured Vehicle No :	SLB8297E
Date of Loss:	29/06/2021	Nature of Claim:	TP
		Claim No:	6443346298SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX1520C	Engine No:	CTH229642
Make & Model:	VOLKSWAGEN TIGUAN, 1.4 TSI (A)	Chassis No:	WVGZZZ5NZGW026437
Reg. Date:	27/11/2015 (Man. Year: 2015)	Odometer:	99397 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,580.52	5,543.33	4,037.19	42.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	840.00	2,110.00	71.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,530.52	6,383.33	6,147.19	49.06
Approved Total (Overridden) (S\$)		5,100.00		

Nett Amount (S\$)	12,530.52	5,100.00	7,430.52	59.30
		+ Car Rental (7.0 x S\$100.00/day) (S\$)	700.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	5,807.45	

INSPECTION

Date of Assignment: 02/07/2021

Date Inspected: 05/07/2021

Estimated Period of Repair: 4.0 days

Inspected At: Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884 EUNOSVILLE
Singapore 400832

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (ASSY)	Deformed/ Torn	1,786.05 FL	*1,466.01 FL
2	1		*FRONT BUMPER SIDE GARNISH LH	Grazed	268.92 FL	*155.20 FL
3	1		*FRONT BUMPER FOAM	Not Necessary	286.11 FL	*- FL
4	1		*FRONT BUMPER CENTRE MOUNT	Cracked	286.32 FL	*286.32 FL
5	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	254.65 FL	*68.50 FL
6	1		*SET FRONT BUMPER SENSOR RING	Not Necessary	45.72 FL	*- FL
7	1		*FRONT BUMPER ANGLE SENSOR	Not Necessary	286.00 FL	*- FL
8	1		*FRONT BUMPER ARC GARNISH LH	Broken	197.86 FL	*197.86 FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	720.10 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	66.00 FL	*50.00 FL
11	1		*REAR FENDER LH	Dented / Bent	1,186.21 FL	*822.05 FL
12	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	296.42 FL	*- FL
13	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
14	1		*FRONT FENDER ARC GARNISH LH	Grazed	298.72 FL	*298.72 FL
15	1		*FRONT HEADLAMP LH	Cracked	2,682.45 FL	*2,620.15 FL
16	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	115.86 FL	*- FL
17	1		*FRONT TYRE N/S (LOCAL PURCHASE) (\$250.00) (70%)	Cut / Punctured	1,185.00 FS	*175.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,022.39	6,139.81
- List Item Discount on L Items 5.00/10.00% (\$\$)	441.87	596.48
Total Parts (\$\$)	9,580.52	5,543.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,100.00	300.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,000.00	400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO CONDUCT ALL WHEEL ALIGNMENT	New	150.00	80.00
5	TO DIAGNOSTIC & RESET TO SPECIFICATION	New	450.00	0.00
6	TO RUST PROOF AFFECTED AREAS	New	200.00	40.00
Gross Labour Cost (\$\$)			2,950.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >