

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/A1621007286/453

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SK X1520Cat Workshop m/s 200m

of _____

Insured: SLB 8287E

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: £64k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

902B

Vehicle: IN / OUT

Date: _____ Person Contacted: AngelaVeh No: SKX1520CYr Regn: 27/11/15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Volkswagen Tiguan C.C. 1390Colour: white A/C: Insured / Std / NI / NASp. Reading: 99397 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG2225N26W026437Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or offBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim or

Tyre Size: F: _____

R: 255/40 R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7Rear 7

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 7 mmL/Bal. 7 mmD.O.A. 29/6/21D.O.I. 5/7/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orMS L1 2The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 847105

1/4/21 1/5 £5100 Confirmed with E.I.A

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format: _____

Lum Sum / I.B.I.: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

S + RS. \$ _____

Photos _____

Others _____

TOTAL

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunice Spring
#05-1339 Singapore 470130
Tel: 9450 7920
@zoomautowerks@gmail.com

ceci

Not Authorized
Haven
5/3/21

1/s 85100
4 days
Zak phs Hls again

Car Number: SKX1520C

Model: VW Tiguan

Damaged Area: (Front Left Damaged)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

Parts / Material:

1	Front Bumper	QSSy	De/To/1n	1466.01
2	Front Bumper Side Garnish LH	groed		155.20
3	Front Bumper Foam	1n		
4	Front Bumper Centre Mount	one		
5	Front Bumper Mount LH side retain nls	but	68.50	
6	Front Bumper Sensor Ring Set	1n		
7	Front Bumper Angle Sensor @ 286.00	1n		
8	Front Bumper Arc Garnish LH	Sho		
9	Front Bumper Reinforcement	1n		
10	Front Bumper Clips Set	1n	50.00	
11	Front Fender LH	oo/3urf	822.05	
12	Front Fender Inner Shield LH	1n		
13	Front Fender Inner Shield Clips	1n		
14	Front Fender Arc Garnish LH	groed		
15	Front Headlamp LH	one	2620.15	
16	Front Headlamp Lower Bracket LH	1n		

\$	1,786.05	✓
\$	268.92	✓
\$	286.11	X
\$	286.32	✓
\$	254.65	✓
\$	45.72	X
\$	286.00	X
\$	197.86	✓
\$	720.10	X
\$	66.00	✓
\$	1,186.21	✓
\$	296.42	X
\$	60.00	X
\$	298.72	✓
\$	2,682.45	✓
\$	115.86	✓

Parts: \$ 8,837.39

Less Parts 5%: \$ 441.86

Total Parts: \$ 8,395.52

10%

Special Net Items:

Front: tyre nls

AP250

cur/pun \$ 1,185.00 70% 175 s/n
Total S/N Parts: \$ 1,185.00

Labour:

To Remove, Repair & Renew Affected Accident Areas
To Putty, Spray Paint on Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Conduct All Wheel Alignment
To Diagnostic & Reset to Specification
To Rust Proof Affected Areas

\$	1,100.00	300
\$	1,000.00	400
\$	50.00	20
\$	150.00	80
\$	450.00	X
\$	200.00	40

Total Labour: \$ 2,950.00

TOTAL PARTS:	\$	8,395.52
TOTAL SPECIAL NET ITEM:	\$	1,185.00
TOTAL LABOUR:	\$	2,950.00
TOTAL REPAIR COST:	\$	12,530.52

P-5964.81
10%
P-536832

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM:

RECOMMENDED NUMBER OF DAYS:

SURVEY BY / SURVEYOR FIRM:

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT:

FINALISED AMOUNT:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S-N-17K
L-840
63833

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SKX1620C ←
Date 5.7.21 13:53

Volkswagen : Tiguan : 2008- (5N) : Front Wheel Drive : Standard Suspension (G02 G10)

Front : Left

Actual	Before	Specified Range
-3°19'		-0°57' 0°03'
7°21'		7°04' 8°04'
0°11'		0°00' 0°10'
15°41'		
12°21'		
		-1°56' -1°16'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°58'		-0°57' 0°03'
6°58'		7°04' 8°04'
0°14'		0°00' 0°10'
17°20'		
16°22'		
		-1°56' -1°16'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-2°21'		-0°30' 0°30'
0°23'		-0°30' 0°30'
-1°40'		
0°25'		0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-1°26'		-1°50' -0°50'
-0°07'		0°00' 0°10'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°36'		-1°50' -0°50'
0°04'		0°00' 0°10'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°10'		-0°30' 0°30'
-0°03'		0°00' 0°20'
-0°05'		-0°20' 0°20'

LDW was not adjusted.