

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG21002216/R1VF3E2-1

Date: 07/07/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/20-418829-CA
Claimant Vehicle No :	FBJ7050H	Insured Vehicle No :	FBB9397L
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000087

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ7050H	Engine No:	45SB019529
Make & Model:	YAMAHA FZ16ST, 153cc (M)	Chassis No:	ME145S0BAD2019620
Reg. Date:	16/09/2014 (Man. Year: 2013)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/80-17	Rear Tyre Size:	130/70-17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,935.50	2,055.70	1,879.80	47.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	390.00	240.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,565.50	2,445.70	2,119.80	46.43
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	4,565.50	1,950.00	2,615.50	57.29
+ GST 7.00/7.00% (S\$)	319.59	136.50	183.09	57.29
Nett Amount (S\$)	4,885.09	2,086.50	2,798.59	57.29

INSPECTION

Date of Assignment:	16/02/2021	
Date Inspected:	17/02/2021 Inspected At:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING Singapore 659578
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jul 2021)	
Parts:	N/A	YAMAHA FZ16ST 153cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ7050H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	110.00 FL	*110.00 FL
2	1		*SET HANDLE BAR END	Cut	60.00 FL	*60.00 FL
3	1		*CLUTCH LEVER	Cut	36.00 FL	*36.00 FL
4	1		*BRAKE LEVER	Usable	40.00 FL	*- FL
5	1		*WINDSHIELD	Cut	86.00 FL	*86.00 FL
6	1		*HEAD COWLING	Cracked	208.00 FL	*208.00 FL
7	1		*HEADLIGHT	Grazed	295.00 FL	*295.00 FL
8	1		*FRONT STAY	Serviceable	115.00 FL	*- FL
9	2		*FORK ASSY	Repair	760.00 FL	*- FL
10	1		*FORK UNDER BRACKET	Serviceable	185.00 FL	*- FL
11	1		*FRONT WHEEL AXLE	Cut	45.00 FL	*45.00 FL
12	1		*FRONT BRAKE DISC	Cut	180.00 FL	*180.00 FL
13	1		*INNER PANEL	N/S Warped	108.00 FL	*54.00 FL
14	2		*SIDE INNER COVER	Cracked / Grazed	192.00 FL	*192.00 FL
15	2		*SIDE OUTER PANEL COMPLETE	Cut	148.00 FL	*148.00 FL
16	2		*FRONT SIGNAL LIGHT	Cut	90.00 FL	*90.00 FL
17	1		*AIR GUIDE OUTER COVER	N/S Cut	76.00 FL	*38.00 FL
18	1		*AIR SHROUD	Usable	59.00 FL	*- FL
19	1		*FUEL TANK COVER COMPLETE	N/S Cut	390.00 FL	*195.00 FL
20	2		*BODY SIDE COVER	Broken / Cracked	228.00 FL	*228.00 FL
21	1		*BODY SIDE COVER PANEL	N/S Missing	72.00 FL	*36.00 FL
22	1		*RESONATOR	Cut	69.00 FL	*69.00 FL
23	1		*AIR CLEANER JOINT	Bent	28.00 FL	*28.00 FL
24	1		*GEAR SHIFT PEDAL	Serviceable	62.00 FL	*- FL
25	2		*FRONT FOOTREST	Serviceable	100.00 FL	*- FL
26	1		*MAIN STAND	Repair	124.00 FL	*- FL
27	1		*REAR FENDER (NOT NECESSARY)	Not Consistent With The Impact	154.00 FL	*- FL
28	1		*MUFFLER COVER	Cut	116.00 FL	*116.00 FL
29	1		*MUFFLER CAP	Cut	59.00 FL	*59.00 FL
30	1		*SET STEERING CONE & BEARING	Serviceable	120.00 FS	*- FS
31	1		*FRONT NUMBER STICKER	Cut	20.00 FS	*10.00 FS
32	1		*REAR NUMBER PLATE	Serviceable	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,355.00	2,283.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	419.50	227.30
Total Parts (\$\$)	3,935.50	2,055.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	80.00	40.00
2	ALIGN STEERING COMPONENTS	New	100.00	50.00
3	WORKMANSHIP TO RENEW DAMAGED PARTS	New	450.00	300.00
Gross Labour Cost (S\$)			630.00	390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >