

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI21007297/KQCN2**Date:** 27/10/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ000450
Claimant Vehicle No :	SHC5787U	Insured Vehicle No :	YP1508R
Date of Loss:	01/07/2021	Nature of Claim:	TP
		Claim No:	M2103108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5787U	Engine No:	2ZR2G81209
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDKB3FU903091511
Reg. Date:	16/09/2020 (Man. Year: 2020)	Odometer:	48834 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,396.32	4,845.52	5,550.80	53.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	2,310.00	2,790.00	54.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,496.32	7,155.52	8,340.80	53.82
+ GST 7.00/7.00% (S\$)	1,084.74	500.89	583.85	53.82
Nett Amount (S\$)	16,581.06	7,656.41	8,924.65	53.82

INSPECTION

Date of Assignment:	06/07/2021	
Date Inspected:	02/07/2021	Inspected At: Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$7,155.53

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2021)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5787U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FENDER SUB-ASSY,FRONT RH	Bent	977.80 FL	-	*977.80 FL
2	1		*LINER,FRONT FENDER RH	Serviceable	202.50 FL	-	*- FL
3	1		*EMBLEM,SIDE PANEL,RH	Necessary	54.60 FL	-	*54.60 FL
4	1		*PANEL SUB-ASSY,FRONT DOOR,RH	Bent	1,300.70 FL	-	*1,300.70 FL
5	1		*LOCK ASSY,FRONT DOOR W/MOTOR,RH	Dented	603.20 FL	-	*603.20 FL
6	1		*MOULDING,FRONT DOOR WINDOW FRAME,FRONT RH	Buckled	38.60 FL	-	*38.60 FL
7	1		*FRAME SUB-ASSY,FRONT DOOR OUTSIDE HANDLE,RH	Distorted	193.50 FL	-	*193.50 FL
8	1		*HANDLE ASSY,FRONT DOOR,OUTSIDE RH	Distorted	390.60 FL	-	*390.60 FL
9	1		*MOTOR ASSY,POWER WINDOW REGULATOR RH	Repair	926.00 FL	-	*- FL
10	1		*WEATHERSTRIP,FRONT DOOR OPENING TRIM,RH	Distorted/Dented	321.10 FL	-	*321.10 FL
11	1		*HINGE ASSY,FRONT DOOR,LOWER RH	Repair	110.60 FL	-	*- FL
12	1		*HINGE ASSY,FRONT DOOR,UPPER RH	Repair	97.50 FL	-	*- FL
13	1		*REGULATOR SUB-ASSY,FRONT DOOR WINDOW,RH	Repair	238.30 FL	-	*- FL
14	1		*TAPE,BLACK OUT,NO 2 FRT RH	Necessary	43.50 FL	-	*43.50 FL
15	1		*TAPE,BLACK OUT,NO 1 FRT RH	Necessary	13.30 FL	-	*13.30 FL
16	1		*TAPE,BLACK OUT,NO 3 FRT RH	Necessary	26.30 FL	-	*26.30 FL
17	1		*PANEL SUB-ASSY,REAR DOOR,RH	Bent	1,294.90 FL	-	*1,294.90 FL
18	1		*FRAME SUB-ASSY,REAR DOOR OUTSIDE HANDLE,RH	Serviceable	193.50 FL	-	*- FL
19	1		*HANDLE ASSY,REAR DOOR,OUTSIDE RH	Serviceable	97.40 FL	-	*- FL
20	1		*WEATHERSTRIP,REAR DOOR OPENING TRIM,RH	Serviceable	293.00 FL	-	*- FL
21	1		*MOTOR ASSY,POWER WINDOW REGULATOR,REAR RH	Serviceable	926.00 FL	-	*- FL
22	1		*REGULATOR SUB-ASSY,REAR DOOR WINDOW,RH	Serviceable	206.70 FL	-	*- FL
23	1		*TAPE,BLACK OUT,NO 2 REAR RH	Necessary	34.90 FL	-	*34.90 FL
24	1		*TAPE,BLACK OUT,NO 3 REAR RH	Necessary	15.40 FL	-	*15.40 FL
25	1		*TAPE,BLACK OUT,NO 1 REAR RH	Necessary	21.90 FL	-	*21.90 FL
26	1		*HINGE ASSY,REAR DOOR,LOWER RH	Repair	87.10 FL	-	*- FL
27	1		*HINGE ASSY,REAR DOOR,UPPER RH	Distorted	98.90 FL	-	*98.90 FL
28	1		*PANEL SUB-ASSY,QUARTER,RH	Bent	871.50 FL	-	*871.50 FL
29	1		*LINER,REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	-	*- FL
30	1		*MOULDING ASSY,BODY ROCKER PANEL RH	Serviceable	594.80 FL	-	*- FL
31	1		*REAR FENDER LINER CLIP	Not Necessary	65.00 FS	-	*- FS
32	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	-	*- FS
33	1		*HUB CAP	Serviceable	211.50 FS	-	*- FS
34	1		*RIM	Serviceable	1,879.40 FS	-	*- FS
35	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	-	*60.00 FS
36	1		*DOOR STICKER TEL NO	Necessary	100.00 FS	-	*60.00 FS
37	1		*DOOR TRIM CLIP	Not Necessary	75.00 FS	-	*- FS
38	1		*DOOR WEATHERSTRIP CLIP	Not Necessary	80.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
				Sub Total (\$)	12,999.80	6,420.70	
				- List Item Discount on L Items 25.00/25.00% (\$)	2,603.48	1,575.18	
				Total Parts (\$)	10,396.32		4,845.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	90.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	100.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	1,000.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	1,100.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,100.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >