

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EQI21007298/EUF3E2

**Date:** 16/08/2021

### REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

**Claimant Vehicle No :** XE4345T

**Insured Vehicle No :** XD512J

Date of Loss: 29/06/2021

Nature of Claim: TP

Claim No: DM21HO00950/JT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE4345T**

Make & Model: HINO GH8JR1A 19 TON, 7.7 D (M)

Engine No: J08EWS10155

Reg. Date: 28/09/2018 (Man. Year: 2018)

Chassis No: JHDGH8JR1XXX10213

Colour: White

Odometer: 82094 km

Engine Capacity: 7685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 295/80R22.5

Rear Tyre Size: 295/80R22.5

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,645.43	1,322.09	4,323.34	76.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,250.00	550.00	30.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,445.43</b>	<b>2,572.09</b>	<b>4,873.34</b>	<b>65.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>(S\$)</b>	7,445.43	2,050.00	5,395.43	72.47
<b>+ GST 7.00/7.00% (S\$)</b>	521.18	143.50	377.68	72.47
<b>Nett Amount (S\$)</b>	<b>7,966.61</b>	<b>2,193.50</b>	<b>5,773.11</b>	<b>72.47</b>

### INSPECTION

Date of Assignment: 05/07/2021

Date Inspected: 05/07/2021

Inspected At:

15 Fan Yong Road

Repairer: Mova Automotive Pte Ltd

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Aug 2021)	
<b>Parts:</b>	N/A	HINO GH8JR1A 19 TON 7.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE4345T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP ASSY LH	Broken	180.10 F	*180.10 FL
2	1		*REAR CHASSIS FRAME LH (REPAIR) (NPA)	Repair	-	*- FL
3	1		*REAR STEP PANEL	Not Necessary	800.00 FS	*- FS
4	1		*REVERSE LAMP BRACKET	Not Necessary	60.00 FS	*- FS
5	1		*REVERSE LAMP LH	Not Necessary	71.20 F	*- FL
6	1		*WOODEN TAILLAMP	Dented	1,000.00 FS	*700.00 FS
7	1		*WOODEN TAILGATE LOCK LH	Missing	150.00 FS	*120.00 FS
8	1		*WOODEN SIDE GATE LH	Not Necessary	1,600.00 FS	*- FS
9	1		*FRONT WOODEN GATE	Broken	1,000.00 FS	*180.00 FS
10	1		*COMPANY STICKER	Necessary	680.00 F	*150.00 FS
11	1		*60 KM/H STICKER	Necessary	10.00 F	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,551.30</b>	<b>1,340.10</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	18.01
<b>+ Margin on L,N Items 10.00/0.00% (\$\$)</b>	94.13	0.00
<b>Total Parts (\$\$)</b>	<b>5,645.43</b>	<b>1,322.09</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REAR WOODEN PLATFORM IN ORDER TO KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER, CUT/WELD REAR STEP PANEL, REMOVE & REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION	New	1,500.00	1,000.00
2	SPRAY PAINT REAR STEP PANEL, REAR BRACKET	New	300.00	250.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,800.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >