

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21007302/VUF3E2

Date: 15/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210012989
Claimant Vehicle No :	SLK1451A	Insured Vehicle No :	SMH9434B
Date of Loss:	01/07/2021	Nature of Claim:	TP
		Claim No:	7082239656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK1451A	Engine No:	27491030772970
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2050402R229461
Reg. Date:	06/01/2017 (Man. Year: 2016)	Odometer:	75958 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/07/2021	
Date Inspected:	05/07/2021	Inspected At: Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$116,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Dented	0.00 F	*- F
2	1		*FRT RH DOOR LOCK	Distorted	0.00 F	*- F
3	1		*REAR RH DOOR	Dented	0.00 F	*- F
4	1		*REAR RH DOOR HINGE LOWER	Bent	0.00 F	*- F
5	1		*REAR RH DOOR CHECKER	Bent	0.00 F	*- F
6	1		*POWER WINDOW REGULATOR	Scratched	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >