

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21007304/KQF3E2

**Date:** 10/08/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141343AL2		
<b>Claimant Vehicle No :</b>	SMQ9585B	<b>Insured Vehicle No :</b>	EV36Y		
Date of Loss:	01/07/2021	Nature of Claim:	TP	Claim No:	636839

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ9585B	Engine No:	2ARJ279933
Make & Model:	TOYOTA ALPHARD, 2.5 SC CVT (A)	Chassis No:	AGH300246845
Reg. Date:	12/12/2019 (Man. Year: 2019)	Odometer:	33742 km
Colour:	Metallic Pearl White		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 3 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,722.50	3,757.27	1,965.23	34.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,140.00	1,600.00	58.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,462.50</b>	<b>4,897.27</b>	<b>3,565.23</b>	<b>42.13</b>
<b>+ GST 7.00/7.00% (S\$)</b>	592.38	342.81	249.57	42.13
<b>Nett Amount (S\$)</b>	<b>9,054.88</b>	<b>5,240.08</b>	<b>3,814.80</b>	<b>42.13</b>

### INSPECTION

Date of Assignment:	05/07/2021		
Date Inspected:	19/07/2021	Inspected At:	MBM Wheelpower Pte Ltd (HQ) 176 Sin Ming Drive #01-15 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	5.0 days		

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2021)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 SC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ9585B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	2,250.00 FL	*- FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	95.00 FL	*95.00 FL
3	1		*FRONT BUMPER RH CHROME	Cracked	210.00 FL	*118.00 FL
4	1		*HEAD LAMP RH	Mtg Cracked	4,050.00 FL	*3,831.70 FL
5	1		*HEAD LAMP RH CHROME	Mtg Cracked	210.00 FL	*210.00 FL
6	1		*FRONT RH FENDER	Buckled	680.00 FL	*680.00 FL
7	10		*BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
8	1		*FRONT RH FENDER BRACKET	Bent	75.00 FL	*75.00 FL
					Sub Total (S\$)	7,630.00 5,009.70
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,907.50 1,252.43
					Total Parts (S\$)	5,722.50 3,757.27

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,000.00	400.00
2	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	New	300.00	0.00
3	TO APPLY ANTI RUST COATING	New	150.00	30.00
4	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	0.00
5	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	660.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS	New	150.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,740.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >