

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 22 Jul 2021

Preliminary Advice

Insured Vehicle No	: EV36Y	Accident Date	: 01/07/2021
TP Vehicle No	: SMQ9585B	Assignment Date	: 05/07/2021
Make	: TOYOTA ALPHARD	Est. Duration of Repair	: 5
Date of Inspection	: 19/07/2021		
Inspection At	: MBM WHEELPOWER PTE LTD (HQ) 160 SIN MING DRIVE #06-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,256.25
Revised Amount	:S\$	5,043.75
Check Items (Estimated)	:S\$	2,092.50
Total	:S\$	7,136.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.