

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21007306/AEA3Q2**Date:** 27/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	FBR4215C	Insured Vehicle No :	SLP3598X
Date of Loss:	29/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR4215C	Engine No:	H336E0078538
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Chassis No:	MH3SH0840LK010417
Reg. Date:	08/06/2020 (Man. Year: 2020)	Odometer:	67218 km
Colour:	Grey		
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	140/70 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,888.00	5,724.70	2,163.30	27.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	920.00	960.00	51.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,768.00	6,644.70	3,123.30	31.97
+ GST 7.00/7.00% (S\$)	683.76	465.13	218.63	31.97
Nett Amount (S\$)	10,451.76	7,109.83	3,341.93	31.97
+ Loss of Use (5.0 x S\$35.00/day) (S\$)		175.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,292.28		

INSPECTION

Date of Assignment:	05/07/2021		
Date Inspected:	06/07/2021	Inspected At:	Kivile Enterprise (HQ) BLK 3007 UBI RD 1 #01-408 Singapore 408701
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Oct 2021)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR4215C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	155.00 F	*- FL
2	1		*MIRROR SET (RH)	Cut	90.00 F	*90.00 FL
3	1		*SET LEVER	Cut	96.00 F	*96.00 FL
4	1		*SET BALANCER	Not Necessary	80.00 F	*- FL
5	1		*WIND SCREEN	Missing	280.00 F	*250.00 FL
6	1		*WIND SCREEN HOLDER	Necessary	98.00 F	*98.00 FL
7	1		*TOP BELTING COVER	Cut	85.00 F	*85.00 FL
8	1		*LOWER BELTING COVER	Cut	85.00 F	*85.00 FL
9	1		*HEAD LIGHT	Cut	580.00 F	*550.00 FL
10	1		*FAIRING STAY	Bent	180.00 F	*180.00 FL
11	1		*FRONT FAIRING RH	Cracked	220.00 F	*220.00 FL
12	1		*SIGNAL LIGHT RH	Cracked	75.00 F	*75.00 FL
13	1		*SIGNAL LIGHT GARNISH	Cut	65.00 F	*65.00 FL
14	1		*FOOT PADDLE TOP RH	Deformed	78.00 F	*78.00 FL
15	1		*FOOT PADDLE LOWER RH	Cut	78.00 F	*78.00 FL
16	1		*SIDE FAIRING RH	Cracked	280.00 F	*280.00 FL
17	1		*FORK INNER TUBE	Bent	450.00 F	*450.00 FL
18	1		*FORK OUTER TUBE	O/S Cut	550.00 F	*275.00 FL
19	1		*FORK PROTRACTOR RH	Cracked	155.00 F	*155.00 FL
20	1		*FORK LOWER CLAMP	Damaged	420.00 F	*420.00 FL
21	1		*STEERING CONE	Damaged	130.00 F	*130.00 FL
22	1		*DISC	Warped	180.00 F	*180.00 FL
23	1		*RIM	Not Necessary	650.00 F	*- FL
24	1		*SEAT BAR	Cut	180.00 F	*180.00 FL
25	1		*SIDE COVER RH	Cracked	185.00 F	*185.00 FL
26	1		*BOX	Cut	180.00 F	*180.00 FL
27	1		*EXHAUST PIPE	Dented	580.00 F	*530.00 FL
28	1		*EXHAUST PIPE COVER	Cracked	220.00 F	*220.00 FL
29	1		*REAR FOOTREST RH	Cut	78.00 F	*78.00 FL
30	1		*MAIN STAND	Not Necessary	150.00 F	*- FL
31	1		*REAR ABSORBER	Bent	660.00 F	*600.00 FL
32	1		*REAR ENGINE MOUNTING	Torn	480.00 F	*420.00 FL
33	1		*LOGO	Necessary	80.00 FS	*80.00 FS
34	1		*FRONT NUMBER PLATE	Missing	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,888.00	6,348.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	623.30
Total Parts (\$\$)	7,888.00	5,724.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REAR BODY FRAME REPAIR	New	380.00	250.00
2	REAR BODY FRAME RESPRAY	New	350.00	150.00
3	FAIRING RESPRAY	New	550.00	280.00
4	LABOUR	New	550.00	200.00
5	TRANSPORT	New	50.00	40.00
Gross Labour Cost (\$)			1,880.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >