

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007309/T1GA3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993604
Claimant Vehicle No :	SHC6362E	Insured Vehicle No :	GBK3711E
Date of Loss:	05/07/2021	Nature of Claim:	TP
		Claim No:	7136195281SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6362E		
Make & Model:	KIA OPTIMA, 1.7 D (A)	Engine No:	D4FDEH313236
Reg. Date:	20/01/2015 (Man. Year: 2014)	Chassis No:	KNAGM414MF5575304
Colour:	Silver	Odometer:	641510 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,273.10	3,819.10	3,454.00	47.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,760.00	2,100.00	54.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,133.10	5,579.10	5,554.00	49.89
Approved Total (Overridden) (S\$)		4,450.00		

(S\$)	11,133.10	4,450.00	6,683.10	60.03
+ GST 7.00/7.00% (S\$)	779.32	311.50	467.82	60.03
Nett Amount (S\$)	11,912.42	4,761.50	7,150.92	60.03
+ Loss of Use (5.0 x S\$40.00/day) (S\$)		200.00		
+ Car Rental (5.0 x S\$60.99/day) (S\$)		304.95		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,273.90		
Global Sum Settlement (S\$)		5,250.00		

INSPECTION

Date of Assignment: 05/07/2021

Date Inspected: 05/07/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S HEAD LAMP	Cracked	1,028.00 FL	*1,028.00 FL
2	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
3	1		*FRONT BUMPER EMBLEM	Deformed	531.00 FL	*531.00 FL
4	1		*FRONT BUMPER N/S & O/S SIDE RETAINER	N/S Not Necessary /O/S Deformed	32.00 FL	*16.00 FL
5	1		*FRONT BUMPER N/S & O/S UPPER BRACKET	N/S Not Necessary/O/S Necessary	32.00 FL	*16.00 FL
6	1		*FRONT BUMPER N/S & O/S SUPPORT BRACKET	N/S Not Necessary/O/S Necessary	32.00 FL	*16.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	328.00 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	110.00 FL	*- FL
9	1		*FRONT BUMPER O/S PROTECTOR	Cut	51.00 FL	*51.00 FL
10	1		*FRONT BUMPER O/S FOG LAMP COVER	Deformed	66.00 FL	*66.00 FL
11	1		*FRONT BUMPER LOWER STIFFER	Not Necessary	134.00 FL	*- FL
12	1		*FRONT BUMPER LOWER LIP	Deformed	40.00 FL	*40.00 FL
13	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	174.00 FL	*- FL
14	1		*WASHER TANK	Deformed	47.00 FL	*47.00 FL
15	1		*WASHER TANK MOTOR	Not Necessary	48.00 FL	*- FL
16	1		*SUPPORT PANEL	Bent	645.00 FL	*645.00 FL
17	1		*BONNET	Bent	979.00 FL	*979.00 FL
18	2		*BONNET HINGE	Repair	94.00 FL	*- FL
19	1		*BONNET GRILLE	Not Necessary	385.00 FL	*- FL
20	1		*FRONT O/S FENDER	Bent	384.00 FL	*384.00 FL
21	1		*FRONT O/S FENDER INNER SHIELD	Torn	120.00 FL	*120.00 FL
22	1		*FRONT O/S WHEEL HOUSE	Repair	474.00 FL	*- FL
23	1		*FRONT O/S LOWER ARM	Not Necessary	439.00 FL	*- FL
24	1		*FRONT O/S SHOCK ABSORBER	Not Necessary	330.00 FL	*- FL
25	1		*FRONT O/S BALL JOINT	Not Necessary	59.00 FL	*- FL
26	1		*FRONT O/S TIE ROD END	Not Necessary	61.00 FL	*- FL
27	1		*FRONT O/S KNUCKLE BEARING	Not Necessary	157.00 FL	*- FL
28	1		*FRONT O/S STABILIZER LINK	Not Necessary	86.00 FL	*- FL
29	1		*FRONT O/S KNUCKLE ARM	Not Necessary	547.00 FL	*- FL
30	1		*FRONT O/S RIM	Not Necessary	246.00 FL	*- FL
31	1		*FRONT O/S WHEEL COVER	Cut	116.00 FL	*116.00 FL
32	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Necessary	28.00 FS	*10.00 FS
33	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
34	1		*FRONT O/S FENDER STICKER	Necessary	60.00 FS	*40.00 FS
35	1		*FRT O/S DOOR STICKER	Necessary	100.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

F=Franchise part. S=SpcNett. L=ListItemDisc.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=1017418&extid=365281&CFID=88245381&CFTOKEN=97e46483ce2b99bf-0B02ED44-A9E1-D0C6-D4DF99... 4/5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	50.00	50.00
2	TO CHECK WHEEL ALIGNMENT	New	80.00	80.00
3	TO DISMANTLE AND REPLACE FRONT O/S UNDERCARRIAGE	New	250.00	0.00
4	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
5	TO LIFT ENGINE TO FACILITATE REPAIR ON THE FRONT O/S WHEEL HOUSE	New	350.00	0.00
6	TO DISMANTLE THE DASHBOARD TO FACILITATE REPAIR ON THE FRONT O/S WHEEL HOUSE	New	350.00	0.00
7	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO CUT/WELD AND HEAT ON THE FRONT O/S WHEEL HOUSE .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE FRONT O/S CHASSIS MEMBER SAME ETC	New	1,200.00	700.00
8	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,BONNET ,BONNET GRILLE ,FRONT O/S FENDER ,FRONT O/S WHEEL HOUSE ,FRONT O/S CHASSIS MEMBER	New	1,200.00	900.00
9	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	30.00
Gross Labour Cost (\$\$)			3,860.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >