

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007310/T1PA3Q2
Date: 08/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700069865
Claimant Vehicle No :	SHA2205M	Insured Vehicle No :	SLT5642S
Date of Loss:	01/07/2021	Nature of Claim:	TP
		Claim No:	4418377882SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2205M	Engine No:	G4LEKU298721
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU164992
Reg. Date:	01/08/2019 (Man. Year: 2019)	Odometer:	130938 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,159.52	0.00	1,159.52	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,270.00	850.00	420.00	33.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,429.52	850.00	1,579.52	65.01
+ GST 7.00/7.00% (S\$)	170.07	59.50	110.57	65.01

Nett Amount (S\$)	2,599.59	909.50	1,690.09	65.01
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,437.07		
Global Sum Settlement (S\$)		1,430.00		

INSPECTION

Date of Assignment: 02/07/2021

Date Inspected: 05/07/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER COVER	Repair	430.90 FL	*- FL	
2	1		*FRONT BUMPER CENTRE MOULDING	Not Necessary	368.50 FL	*- FL	
3	1		*FRONT BUMPER BRACKET LH	Not Necessary	35.00 FL	*- FL	
4	1		*FRONT FENDER LH	Repair	588.80 FL	*- FL	
5	1		*FRONT FENDER EMBLEM LH	Not Necessary	26.20 FL	*- FL	
F=Franchise part. L=ListItemDisc.							
					Sub Total (S\$)	1,449.40	0.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	289.88	0.00
					Total Parts (S\$)	1,159.52	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	550.00	350.00
2	SPRAY PAINT	New	600.00	500.00
3	RESET FRONT WHEEL ALIGNMENT	New	60.00	0.00
4	CHECK LIGHTING	New	60.00	0.00
Gross Labour Cost (S\$)			1,270.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >