

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007311/KRA3Q2**Date:** 14/12/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBC7991D**Insured Vehicle No :** SLM6166E

Date of Loss: 30/06/2021

Nature of Claim: TP

Claim No: 8061395700SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC7991D**

Make & Model: NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)

Engine No: K9KF276D127186

Reg. Date: 24/10/2013 (Man. Year: 2013)

Chassis No: VSKYBAM20U0059480

Colour: White

Odometer: 205228 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,255.30	2,639.34	615.96	18.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,100.00	500.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,855.30	3,739.34	1,115.96	22.98
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	4,855.30	2,950.00	1,905.30	39.24
+ GST 7.00/7.00% (S\$)	339.87	206.50	133.37	39.24
Nett Amount (S\$)	5,195.17	3,156.50	2,038.67	39.24
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,463.95		

INSPECTION

Date of Assignment: 02/07/2021

Date Inspected: 05/07/2021 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR ,LH	Bent	1,567.10 FN	*1,281.90 FN
2	1		*REAR DOOR HINGE	Repair	177.60 FN	*- FN
3	1		*REAR DOOR LOCK	Repair	98.80 FN	*- FN
4	1		*REAR BUMPER	Buckled / Dented	624.80 FN	*624.80 FN
5	1		*REAR DOOR ,RH	Bent	1,083.70 FN	*960.90 FN
6	1		*NV200 EMBLEM	Necessary	65.00 FN	*65.00 FN

F=Franchise part. N=NettItemDisc.

	Sub Total (S\$)	3,617.00	2,932.60
- Nett Item Discount on N Items 10.00/10.00% (S\$)	361.70	293.26	
	Total Parts (S\$)	3,255.30	2,639.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	COMPANY STICKER	New	120.00	80.00
2	TO TRANSFER REAR DOORS GLASS (2 DRS) TO NEW DOOR	New	180.00	120.00
3	TO REMOVE DAMAGED DOORS AND ATTACHMENTS TO REPAIR /STRAIGHTEN REAR CHASSIS TO REPLACE /ALIGN DOORS	New	600.00	500.00
4	TO SPRAY PAINT	New	700.00	400.00
Gross Labour Cost (\$\$)			1,600.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >