

INVOICE

TO: GRAB RENTALS PTE LTD

C/O: PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD, SINGAPORE 628800 Invoice No.:

0220/PE452

PO Number.:

PO20/03-1200

Date:

17-Mar-2020

PARTICULARS

Vehicle Registration No.:

SLP 4487 B

Date of Loss:

06-Mar-2020

Date of Assessment:

06-Mar-2020

SERVICES

FEES

1. Assessment with report Photographs - Including films, developing, storage and Transport.

\$550.00


TOTAL

\$550.00

SINGAPORE DOLLARS FIVE HUNDRED FIFTY ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chal Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO:

GRAB RENTALS PTE LTD

C/O: PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD, SINGAPORE 628800 Our Reference:

0220/PE452

Date:

17-Mar-2020

ASSESSMENT OF VEHICLE NO. SLP 4487 B

DATE OF LOSS:

06-Mar-2020

We have carried out a physical assessment at PEGASUS ENGINEERING & TRADING PTE LTD,

74 Kian Teck Road, Singapore 628800, according to your instruction

on

06-Mar-2020

and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.:

SLP 4487 B

Make & Model:

MAZDA3 SEDAN 1.5 AT EU6

Year of Registration:

2017

Engine Capacity:

1496

Chassis No.:

JM6BN22A8H0152961

Engine No.:

P520444623

Colour:

GREY

Mileage (km):

173469

2. VEHICLE CONDITION

Body Paint:

GOOD

Steering:

SERVICEABLE

Foot Brake:

SERVICEABLE

Parking Brake: Modification: SERVICEABLE NIL

3, TYRE PARTICULARS & CONDITION

Front

RH Make/Size/Thread:

WESTLAKE

205/60 R16 - 70%

LH Make/Size/Thread:

WESTLAKE

205/60 R16-70%

Rear

RH Make/Size/Thread:

TRIANGLE

205/60 R16-75%

LH Make/Size/Thread:

TRIANGLE

205/60 R16-75%

AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT and REAR portion.

5. REMARKS

Market Value:

Na

Salvage Value:

Na

Repair Limit:

Na

Estimated Amount:

\$16,525.28

Adjusted Amount:

\$11,722.08

Lump Sum:

\$9,300.00

Estimated Repair Days:


12 days

Pursuant to your instruction, we have $\underline{\text{NOT AUTHORISED}}$ repair. The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.



This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.



AEON AUTO CONSULTANTS LLP 50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone:+65 97687958 Facsimile:+65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. SLP 4487 B

PARTS (LIST ITEMS)

QW Description Condition Estimate Assessment 1 FRONT TOP GRILLE COVER Cracked 340.00 340.00 6 FRONT TOP GRILLE COVER RIVET Necessary 5.00 5.00 1 FRONT GRILLE LOWER BASE Necessary 5.00 5.00 2 FRONT GRILLE LOWER BASE CLIP Necessary 5.00 5.00 6 FRONT GRILLE CLIP Necessary 10.00 190.00 6 FRONT GRILLE WHITE CLIP HOLDER Necessary 5.00 5.00 2 FRONT GRILLE BRACKET Necessary 5.00 5.00 4 FRONT GRILLE RIVET Necessary 5.00 5.00 4 FRONT GRILLE RIVET Necessary 60.00 60.00 2 FRONT GRILLE LOGO' EMBLEM Cracked 45.00 45.00 2 FRONT GRILLE CHROME MOULDING Cracked 198.00 198.00 2 FRONT GRILLE CHROME MOULDING BASE Cracked 19.00 45.00 2 FRONT GRILLE CHROME MOULDING BA	AKIS	(FIST LIEINIS)		Workshop's	Our
FRONT TOP GRILLE COVER RIVET	Qtv	Description	Condition		
FRONT TOP GRILLE LOWER BASE Cracked 185.00 185.0	1	FRONT TOP GRILLE COVER	Cracked		
FRONT GRILLE LOWER BASE S.00 S.00			Necessary		
FRONT GRILLE LOWER BASE CLIP	_		Cracked		
FRONT GRILLE CIP Necessary 10.00 10.00			Necessary		
FRONT GRILLE CLIP Necessary 5.00 5.00	_		Cracked		
2 FRONT GRILLE WHITE CLIP HOLDER Necessary 5.00 45.00 2 FRONT GRILLE BRACKET Bent 45.00 45.00 4 FRONT GRILLE BRACKET Necessary 5.00 5.00 5 FRONT GRILLE PIN Necessary 60.00 60.00 1 FRONT GRILLE CHOOME MED Necessary 60.00 45.00 2 FRONT GRILLE SIDE COVER Cracked 45.00 45.00 2 FRONT GRILLE CHROME MOULDING Cracked 198.00 198.00 2 FRONT GRILLE CHROME MOULDING BASE Cracked 65.00 65.00 2 FRONT GRILLE CHROME MOULDING BASE Cracked 1,075.00 1,075.00 3 FRONT BLIME CHROME MOULDING BASE Cracked 1,075.00 1,075.00 4 FRONT BLIME CHROME MOULDING BASE Cracked 1,075.00 1,075.00 5 FRONT BLIME CHROME MOULDING BASE Cracked 1,075.00 1,075.00 1 FRONT BUMPER REAL Bent 168.00 168.00 1		•	Necessary		
FRONT GRILLE BRACKET		• • • • • • • • • • • • • • • • • • • •	Necessary	•	
4 FRONT GRILLE PIN Necessary 5.00 5.00 2 FRONT GRILLE RIVET Necessary 15.00 15.00 1 FRONT GRILLE 'LOGO' EMBLEM Cracked 45.00 45.00 2 FRONT GRILLE CHROME MOULDING Cracked 198.00 198.00 2 FRONT GRILLE CHROME MOULDING BASE Cracked 1,075.00 1,075.00 1 FRONT LH HEADLAMP Necessary 4.00 4.00 3 FRONT LH HEADLAMP CLIP Necessary 4.00 4.00 1 FRONT BUMPER Bent 168.00 168.00 1 FRONT BUMPER Bent 70.00 70.00 2 FRONT BUMPER BRACKET Bent 70.00 70.00 2 FRONT BUMPER BRACKET Bent 45.00 45.00 2 FRONT BUMPER CLIP Necessary 4.00 4.00 2 FRONT BUMPER LOWER GRILLE SIDE COVER Faulty 218.00 218.00 3 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked			Bent		
15.00 15.0	_		Necessary		
FRONT GRILLE 'LOGO' EMBLEM	-		Necessary		
PRONT GRILLE SIDE COVER					
2 FRONT GRILLE CHROME MOULDING Cracked 198.00 2 FRONT GRILLE CHROME MOULDING BASE Cracked 65.00 65.00 1 FRONT LH HEADLAMP Necessary 4.00 4.00 3 FRONT LH HEADLAMP CLIP Bent 168.00 168.00 1 FRONT BUMPER Bent 70.00 70.00 2 FRONT BUMPER SIDE RETAINER L/R Bent 45.00 45.00 2 FRONT BUMPER BRACKET Bent 45.00 45.00 2 FRONT BUMPER CLIP Necessary 4.00 40.00 2 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 48.00 48.00 3 FRONT BUMPER LOWER GRILLE SIDE COVER Faulty 218.00 218.00 4 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 48.00 48.00 5 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 108.00 108.00 6 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 108.00 35.00 1 FRONT BUMPER LOGIAMP			Cracked		
2 FRONT GRILLE CHROME MOULDING BASE Cracked 1,075.00 1,075.00 1 FRONT LH HEADLAMP Necessary 4.00 4.00 3 FRONT LH HEADLAMP CLIP Bent 168.00 4.00 1 FRONT BLMPER Bent 168.00 866.80 1 FRONT BUMPER Bent 70.00 70.00 2 FRONT BUMPER SIDE RETAINER L/R Bent 45.00 45.00 2 FRONT BUMPER BRACKET Bent 45.00 45.00 10 FRONT BUMPER CLIP Cracked 48.00 48.00 2 FRONT BUMPER CLIP Cracked 48.00 48.00 3 FRONT BUMPER LOWER GRILLE SIDE COVER Faulty 218.00 218.00 1 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 48.00 48.00 1 FRONT BUMPER LH FOGLAMP Cracked 108.00 108.00 1 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION Cracked 35.00 35.00 1 FRONT BUMPER LH FOGLAMP BRACKET			Cracked		
FRONT LH HEADLAMP			Cracked		
RECORD TO BUMPER LH FOGLAMP BRACKET RECORD TRONT BUMPER LH FOGLAMP BRACKET RECORD TO BUMPER LH FOGLAMP BRACKET Bent Augustation Au			Cracked	•	•
1 FRONT LH HEADLAMP PANEL Bent 168.00 168.00 1 FRONT BUMPER Cracked 866.80 866.80 2 FRONT BUMPER SIDE RETAINER L/R Bent 70.00 70.00 2 FRONT BUMPER BRACKET Bent 45.00 45.00 10 FRONT BUMPER CLIP Necessary 4.00 4.00 2 FRONT BUMPER LOWER GRILLE SIDE COVER Faulty 218.00 218.00 1 FRONT BUMPER LH FOGLAMP Cracked 108.00 108.00 1 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION Cracked 35.00 35.00 1 FRONT BUMPER LH FOGLAMP BRACKET Bent 40.00 40.00 1 FRONT BUMPER LH FOGLAMP BRACKET Necessary 68.00 68.00 1 FRONT BUMPER TOW HOOK COVER Necessary 68.00 68.00 1 FRONT BUMPER RIGINE UNDER CENTER COVER CLIP Necessary 4.00 4.00 1 FRONT BUMPER RIGINE UNDER CENTER COVER CLIP Repair 545.00 - <td< td=""><td></td><td></td><td>Necessary</td><td></td><td></td></td<>			Necessary		
1 FRONT BUMPER Cracked 360.60 360.60 2 FRONT BUMPER SIDE RETAINER L/R Bent 70.00 70:00 2 FRONT BUMPER BRACKET Bent 45.00 45.00 10 FRONT BUMPER CLIP Necessary 4.00 4.00 2 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 48.00 48.00 1 FRONT BUMPER LH FOGLAMP Cracked 108.00 108.00 1 FRONT BUMPER LH FOGLAMP COVER Cracked 35.00 35.00 1 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION Cracked 35.00 35.00 1 FRONT BUMPER LH FOGLAMP BRACKET Bent 40.00 40.00 1 FRONT BUMPER TOW HOOK COVER Necessary 68.00 68.00 1 FRONT BUMPER ENGINE UNDER CENTER COVER Cracked 295.00 295.00 1 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP Necessary 4.00 4.00 1 FRONT BUMPER REINFORCEMENT Repair 545.00 - 1 FRONT SUPPORT TOP COVER Cracked 158.00 - 6 FRONT SUPPORT TOP COVER CLIPS Necessary 5.00			Bent		
PRONT BUMPER SIDE RETAINER L/R PRONT BUMPER BRACKET Bent 45.00 45.00 10 FRONT BUMPER CLIP FRONT BUMPER CLIP FRONT BUMPER LOWER GRILLE SIDE COVER FRONT BUMPER LH FOGLAMP FRONT BUMPER LH FOGLAMP FRONT BUMPER LH FOGLAMP COVER FRONT BUMPER LH FOGLAMP GARNISH EXTENTION FRONT BUMPER LH FOGLAMP BRACKET FRONT BUMPER LH FOGLAMP BRACKET FRONT BUMPER LH FOGLAMP BRACKET FRONT BUMPER TOW HOOK COVER FRONT BUMPER RENGINE UNDER CENTER COVER FRONT BUMPER ENGINE UNDER CENTER COVER FRONT BUMPER ENGINE UNDER CENTER COVER CLIP FRONT BUMPER REINFORCEMENT FRONT BUMPER REINFORCEMENT FRONT SUPPORT TOP COVER REPAIR REPAIR FRONT SUPPORT TOP COVER CLIPS REPAIR REPAIR A58.00 FRONT SUPPORT TOP COVER CLIPS REPAIR REPAIR A58.00 FRONT SUPPORT PANEL			Cracked		
2 FRONT BUMPER BRACKET Bent 43.00 4.00 10 FRONT BUMPER CLIP Necessary 4.00 4.00 2 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 48.00 218.00 1 FRONT BUMPER LH FOGLAMP Cracked 108.00 108.00 1 FRONT BUMPER LH FOGLAMP COVER Cracked 35.00 35.00 1 FRONT BUMPER LH FOGLAMP BRACKET Bent 40.00 40.00 1 FRONT BUMPER TOW HOOK COVER Necessary 68.00 68.00 1 FRONT BUMPER ENGINE UNDER CENTER COVER Cracked 295.00 295.00 1 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP Necessary 4.00 4.00 1 FRONT BUMPER LOWER STIFF Repair 545.00 - 1 FRONT SUPPORT TOP COVER Cracked 158.00 158.00 6 FRONT SUPPORT TOP COVER CLIPS Necessary 5.00 5.00 6 FRONT SUPPORT PANEL Repair 489.00 - 1 <td< td=""><td></td><td></td><td>Bent</td><td></td><td></td></td<>			Bent		
10 FRONT BUMPER CLIP 2 FRONT BUMPER LOWER GRILLE SIDE COVER 3 FRONT BUMPER LH FOGLAMP 48.00 48.00 1 FRONT BUMPER LH FOGLAMP 1 FRONT BUMPER LH FOGLAMP COVER 2 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION 3 FRONT BUMPER LH FOGLAMP BRACKET 40.00 40.00 1 FRONT BUMPER TOW HOOK COVER 4 FRONT BUMPER TOW HOOK COVER 5 FRONT BUMPER ENGINE UNDER CENTER COVER 6 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP 7 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP 8 FRONT BUMPER LOWER STIFF 9 FRONT BUMPER REINFORCEMENT 1 FRONT SUPPORT TOP COVER 1 FRONT SUPPORT TOP COVER 2 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT TOP COVER CLIPS 2 FRONT SUPPORT PANEL 4.00 5 FRONT SUPPORT PANEL 6 FRONT SUPPORT PANEL 7 FRONT SUPPORT PANEL 7 FRONT SUPPORT PANEL			Bent		
2 FRONT BUMPER LOWER GRILLE SIDE COVER Cracked 48.00 218.00 1 FRONT BUMPER LH FOGLAMP Cracked 108.00 108.00 1 FRONT BUMPER LH FOGLAMP COVER Cracked 35.00 35.00 1 FRONT BUMPER LH FOGLAMP BRACKET Bent 40.00 40.00 1 FRONT BUMPER LH FOGLAMP BRACKET Necessary 68.00 68.00 1 FRONT BUMPER TOW HOOK COVER Cracked 295.00 295.00 1 FRONT BUMPER ENGINE UNDER CENTER COVER Cracked 295.00 4.00 10 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP Necessary 4.00 4.00 1 FRONT BUMPER LOWER STIFF Cracked 185.00 185.00 1 FRONT BUMPER REINFORCEMENT Repair 545.00 - 1 FRONT SUPPORT TOP COVER Necessary 5.00 5.00 6 FRONT SUPPORT TOP COVER CLIPS Repair 489.00 - 1 FRONT SUPPORT PANEL 428.00 -			Necessary		
1 FRONT BUMPER LH FOGLAMP 1 FRONT BUMPER LH FOGLAMP COVER 2 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION 2 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION 3 FRONT BUMPER LH FOGLAMP BRACKET 3 Bent 4 0.00 4 0.00 4 FRONT BUMPER TOW HOOK COVER 4 FRONT BUMPER ENGINE UNDER CENTER COVER 5 FRONT BUMPER ENGINE UNDER CENTER COVER 6 FRONT BUMPER LOWER STIFF 7 FRONT BUMPER LOWER STIFF 7 FRONT BUMPER REINFORCEMENT 7 FRONT BUMPER REINFORCEMENT 8 Repair 8 Repair 9 FRONT SUPPORT TOP COVER 9 Repair 1 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT PANEL 1 FRONT SUPPORT PANEL		CRONT BUMPER LOWER GRILLE SIDE COVER	Cracked		
1 FRONT BUMPER LH FOGLAMP COVER 1 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION 2 Cracked 35.00 35.00 1 FRONT BUMPER LH FOGLAMP BRACKET 35.00 35.00 1 FRONT BUMPER LH FOGLAMP BRACKET 35.00 1 FRONT BUMPER TOW HOOK COVER 1 FRONT BUMPER ENGINE UNDER CENTER COVER 10 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP 2 FRONT BUMPER LOWER STIFF 3 Cracked 4.00 4.00 1 FRONT BUMPER LOWER STIFF 4.00 1 FRONT BUMPER REINFORCEMENT 545.00 1 FRONT SUPPORT TOP COVER 5 FRONT SUPPORT TOP COVER 6 FRONT SUPPORT TOP COVER CLIPS 7 Repair 7 FRONT SUPPORT PANEL 7 Repair 7 Repair 7 Support Panel			Faulty		
1 FRONT BUMPER LH FOGLAMP GARNISH EXTENTION 1 FRONT BUMPER LH FOGLAMP BRACKET 295.00 1 FRONT BUMPER TOW HOOK COVER 1 FRONT BUMPER ENGINE UNDER CENTER COVER 295.00 10 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP 1 FRONT BUMPER LOWER STIFF 1 FRONT BUMPER REINFORCEMENT 1 FRONT SUPPORT TOP COVER 1 FRONT SUPPORT TOP COVER CLIPS 2 Repair 2 FRONT SUPPORT TOP COVER CLIPS 3 Stocked 40.00 40.00 68.	-		Cracked		
1 FRONT BUMPER LH FOGLAMP BRACKET 1 FRONT BUMPER TOW HOOK COVER 1 FRONT BUMPER ENGINE UNDER CENTER COVER 295.00 10 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP 1 FRONT BUMPER LOWER STIFF 1 FRONT BUMPER REINFORCEMENT 1 FRONT SUPPORT TOP COVER 6 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT TOP COVER CLIPS 295.00 1 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT TOP COVER CLIPS 295.00 1 FRONT SUPPORT TOP COVER CLIPS 295.00 1 FRONT SUPPORT TOP COVER CLIPS 3 Repair 40.00 40.00 40.00 4.00 4.00 4.00 4.00	_	FRONT BUMBER LH FOGLAMP GARNISH EXTENTION	Cracked		
1 FRONT BUMPER TOW HOOK COVER 1 FRONT BUMPER ENGINE UNDER CENTER COVER 10 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP 1 FRONT BUMPER LOWER STIFF 1 FRONT BUMPER REINFORCEMENT 1 FRONT SUPPORT TOP COVER 1 FRONT SUPPORT TOP COVER CLIPS 295.00 1 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT TOP COVER CLIPS 295.00 295.00 4.00 4.00 4.00 185.00			Bent		
1 FRONT BUMPER ENGINE UNDER CENTER COVER 10 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP Necessary 4.00 4.00 1 FRONT BUMPER LOWER STIFF Cracked 185.00 185.00 1 FRONT BUMPER REINFORCEMENT Repair 545.00 - 1 FRONT SUPPORT TOP COVER CLIPS Necessary 5.00 5.00 6 FRONT SUPPORT TOP COVER CLIPS Repair 489.00 - 1 FRONT SUPPORT PANEL			Necessary		
10 FRONT BUMPER ENGINE UNDER CENTER COVER CLIP 1 FRONT BUMPER LOWER STIFF 2 Cracked 185.00 1 FRONT BUMPER REINFORCEMENT 3 FRONT SUPPORT TOP COVER 4.00 185.00 185.00 1 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT TOP COVER CLIPS 2 Repair 3 FRONT SUPPORT PANEL 428.00 3 FRONT SUPPORT PANEL	_	EPONT BUIMDER ENGINE LINDER CENTER COVER	Cracked		
1 FRONT BUMPER LOWER STIFF Cracked 185.00 105.00 1 FRONT BUMPER REINFORCEMENT Repair 545.00 - 1 FRONT SUPPORT TOP COVER Cracked 158.00 158.00 6 FRONT SUPPORT TOP COVER CLIPS Necessary 5.00 5.00 1 FRONT SUPPORT PANEL Repair 489.00 -		A STATE OF THE COLUMN CALLS	Necessary		
1 FRONT BUMPER REINFORCEMENT 1 FRONT SUPPORT TOP COVER 6 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT PANEL Repair 489.00 - 1 FRONT SUPPORT PANEL Repair 428.00 -			Cracked		
1 FRONT SUPPORT TOP COVER CLIPS 6 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT PANEL Cracked 158.00 158.00 158.00 5.00 6 Repair 489.00 -			Repair		and the second s
6 FRONT SUPPORT TOP COVER CLIPS 1 FRONT SUPPORT PANEL 28.00 -			Cracked		
1 FRONT SUPPORT PANEL Repair 428.00 -	_		Necessary		
Donnie 4/A.UU -			Repair		
			Repair	428.00) -

AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. SLP 4487 B

	DELLA DOCTUR	Bent	1,285.00	1,285.00
1	REAR BOOTLID	Necessary	75.00	75.00
1	REAR BOOTLID 'LOGO' EMBLEM REAR BOOTLID 'MAZDA 3' EMBLEM	Necessary	65.00	65.00
1	REAR BOOTLID 'SKYACTIV' EMBLEM	Necessary	85.00	85.00
1		Bent	155.00	155.00
2	REAR BOOTLID HINGES L/R REAR BOOTLID INNER TRIM BOARD	Cracked	395.00	395.00
1	REAR BOOTLID INNER TRIM BOARD REAR BOOTLID INNER TRIM BOARD CLIP -SET	Necessary	4.00	4.00
1		Cracked	159.00	159.00
1	REAR BOOTLID REFLECTOR LAMP LH	Reuse	159.00	-
1	REAR BOOTLID REFLECTOR CLIPS I /P. SET	Necessary	12.00	12.00
2	REAR BOOTLID REFLECTOR CLIPS L/R - SET	Necessary	15.00	15.00
2	REAR BOOTLID REFLECTOR GASKET L/R	Reuse	148.00	•
1	REAR BOOTLID OUTER LOCK SWITCH	Reuse	95.00	-
2	REAR BOOTLID NUMBER PLATE LAMP L/R	Bent	55.00	55.00
1	REAR BOOTLID LOCK STRIKER	Bent	298.00	298.00
1	REAR BOOTLID MECHANISM LOCK	Bent	25.00	25.00
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R	Cut	198.00	198.00
1	REAR BOOTLID WEATHER STRIP	Cracked	535.00	535.00
1	REAR TAILLAMP LH	Reuse	535.00	-
1	REAR TAILLAMP RH	Necessary	41.80	41.80
2	REAR TAILLAMP INNER RUBBER GASKET L/R	Necessary	10.00	10.00
6	REAR TAILLAMP CLIPS L/R	Repair	1,575.00	-
1	REAR LH FENDER	Repair	990.00	-
2	REAR FENDER INNER TRIM L/R	Necessary	8.00	8.00
20	REAR FENDER INNER TRIM CLIPS L/R	Cracked	310.00	310.00
2	REAR FENDER INNER SHIELD L/R	Necessary.	8.00	8.00
2	REAR FENDER INNER SHIELD CLIPS L/R - SET	Cracked	1,175.00	1,175.00
1	REAR BUMPER	Necessary	4.00	4.00
10		Bent	45.00	45.00
1	REAR BUMPER CENTER BRACKET	Necessary	115.00	115.00
2	REAR BUMPER REFLECTOR L/R	Bent	545.00	545.00
1	REAR BUMPER REINFORCEMENT	Bent	85.00	85.00
2	REAR BUMPER SIDE RETAINER L/R	Necessary	38.00	38.00
2		Cut	125.00	125.00
1		Necessary	4.00	4.00
10		Repair	715.00	
1	REAR END PANEL	vehan		
			16,131.60	10,452.60
		Less 20% discount	3,226.32	2,090.52
		Parts Total:	12,905.28	8,362.08


































































:





