

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007323/T1PA3Q2  
**Date:** 06/01/2022**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070170920   |
| <b>Claimant Vehicle No :</b> | SHA7679X                             | <b>Insured Vehicle No :</b> | SMK8267H     |
| Date of Loss:                | 03/07/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 2486817586SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHA7679X</b>                   |             |                   |
| Make & Model:               | HYUNDAI AE IONIQ HEV DCT, 1.6 (A) | Engine No:  | G4LEKU415620      |
| Reg. Date:                  | 08/01/2021 (Man. Year: 2019)      | Chassis No: | KMHC851CVLU191752 |
| Colour:                     | Blue                              | Odometer:   | 53209 km          |
| Engine Capacity:            | 1580 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 195/65 R15     | Rear Tyre Size:  | 195/65 R15     |
| Front Left Side:  | West Lake 6 mm | Rear Left Side:  | West Lake 6 mm |
| Front Right Side: | West Lake 6 mm | Rear Right Side: | West Lake 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 4,612.58          | 1,126.00          | 3,486.58          | 75.59         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 1,530.00          | 1,085.00          | 445.00            | 29.08         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>6,142.58</b>   | <b>2,211.00</b>   | <b>3,931.58</b>   | <b>64.01</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>429.98</b>     | <b>154.77</b>     | <b>275.21</b>     | <b>64.01</b>  |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>6,572.56</b> | <b>2,365.77</b> | <b>4,206.79</b> | <b>64.01</b> |
| <b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b> |                 | 200.00          |                 |              |
| <b>+ Car Rental (4.0 x S\$125.19/day) (S\$)</b> |                 | 500.76          |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>3,066.53</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>3,050.00</b> |                 |              |

INSPECTION

Date of Assignment: 05/07/2021

Date Inspected: 05/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's  | Amount     |
|-----|-----|----------|--------------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER                         | Cracked       | 459.40 FL   | *459.40 FL |
| 2   | 1   |          | *REAR BUMPER CENTRE MOULDING         | Deformed      | 451.25 FL   | *451.25 FL |
| 3   | 1   |          | *REAR BUMPER REINFORCEMENT           | Not Necessary | 394.80 FL   | *- FL      |
| 4   | 2   |          | *REAR BUMPER STAY LH/RH              | Not Necessary | 276.20 FL   | *- FL      |
| 5   | 1   |          | *REAR BUMPER LOWER CENTRE MOULDING   | Repair        | 155.00 FL   | *- FL      |
| 6   | 1   |          | *REAR BUMPER UNDER LH COVER          | Not Necessary | 108.00 FL   | *- FL      |
| 7   | 10  |          | *REAR BUMPER CLIPS                   | Necessary     | 22.00 FL    | *22.00 FL  |
| 8   | 1   |          | *BOOTLID COVER                       | Repair        | 2,480.40 FL | *- FL      |
| 9   | 1   |          | *BOOTLID LOCK UPPER                  | Not Necessary | 224.00 FL   | *- FL      |
| 10  | 1   |          | *BOOTLID H EMBLEM                    | Not Necessary | 38.00 FL    | *- FL      |
| 11  | 1   |          | *BOOTLID EMBLEM IONID                | Necessary     | 31.80 FL    | *31.80 FL  |
| 12  | 1   |          | *BOOTLID EMBLEM HYBRID               | Necessary     | 24.30 FL    | *24.30 FL  |
| 13  | 1   |          | *BUMPER FOG LAMP                     | Not Necessary | 201.00 FL   | *- FL      |
| 14  | 2   |          | *BUMPER NUMBER LAMP LH/RH            | Not Necessary | 170.60 FL   | *- FL      |
| 15  | 2   |          | *BUMPER HOOK COVER                   | Not Necessary | 94.60 FL    | *- FL      |
| 16  | 2   |          | *REAR REFLECTOR LH/RH                | Not Necessary | 63.53 FL    | *- FL      |
| 17  | 1   |          | *REAR ANTENNA -SMART KEY             | Not Necessary | 40.50 FL    | *- FL      |
| 18  | 2   |          | *REAR BUMPER BRACKET -LH/RH          | Not Necessary | 111.60 FL   | *- FL      |
| 19  | 1   |          | *BOOTLID COMFORT APP STICKER         | Necessary     | 40.00 FS    | *40.00 FS  |
| 20  | 2   |          | *BOOTLID COMFORT /TEL NUMBER STICKER | Necessary     | 60.00 FS    | *60.00 FS  |
| 21  | 1   |          | *REAR NUMBER PLATE W/HOLDER          | Cracked       | 55.00 FS    | *55.00 FS  |
| 22  | 1   |          | *REAR REVERSE SENSOR                 | Not Working   | 180.00 FS   | *180.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>5,681.98</b> | <b>1,323.75</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 1,069.40        | 197.75          |
| <b>Total Parts (\$)</b>                                  | <b>4,612.58</b> | <b>1,126.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                 | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                             |          |                 |                 |
| 1                              | PANEL BEATING               | New      | 750.00          | 525.00          |
| 2                              | SPRAY PAINTING CHARGE       | New      | 600.00          | 500.00          |
| 3                              | CHECK WIRING AND LIGHTING   | New      | 60.00           | 30.00           |
| 4                              | TUFF KOTE                   | New      | 60.00           | 0.00            |
| 5                              | REMOVE/REFIX REVERSE SENSOR | New      | 60.00           | 30.00           |
| <b>Gross Labour Cost (S\$)</b> |                             |          | <b>1,530.00</b> | <b>1,085.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >