

ASS. FRY:

REF: CCG/CTI 21007327/Dra³

ASSIGNMENT

CJE May 2024

From: _____ Date: _____

Estimate Cost: _____

OD / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Work in m/s _____

of _____

Insured _____

Policy # _____

Claimant's _____

Sum Insured _____


Excess: _____

(Check record)

Make of Vehicle: _____

(Police Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Bal. of Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Search _____ Consistent? : Yes or No

Est. Repair: 87 days Res.: Yes or NoLump Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 711XYr Regn: 2019 / MayType: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: ToyotaPrins

CC

1798Colour: YellowA/C: Insured / Std / NASp. Reading: 328583T/Radio: Insured / Std / NAEng/No: 22R2C13891C/No: JTDB33PU203080348Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NTI / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUBARU /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal: S

mm

R/Bal: S

mm

L/Bal: S

mm

L/Bal: S

mm

D.O.A: 03/07/22D.O.I: 05/07/22Survey held at S. Frost Sun Ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Taipei 555 1813P28/7/22 Phone L/S 15,000 - with 8 days of workRepairer changed almost all parts due to difficulty in source of parts used parts.

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Report Format:

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos