3/8/22, 10:57 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21007332/KGS3Q2

**Date:** 08/03/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle SKU1036A Insured Vehicle No: SLQ8757R

Date of Loss: 25/01/2021 Nature of Claim: TP Claim No: MFL2021D0001558

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKU1036A

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRX521184

Reg. Date: 30/06/2015 (Man. Year: 2015) Chassis No: MR053REH104535799

Colour: Metallic Silver Odometer: 91332 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

Global Sum Settlement (S\$)

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,606.10	1,234.12	1,371.98	52.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	460.00	700.00	60.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,766.10	1,694.12	2,071.98	55.02
+ GST 7.00/7.00% (S\$)	263.63	118.59	145.04	55.02
Nett Amount (S\$)	4,029.73	1,812.71	2,217.02	55.02

**INSPECTION** 

Date of Assignment: 05/07/2021

K Kim Hin Automotive Pte Ltd

Date Inspected: 28/07/2021 Inspected At: BLK 34 SIN MING DRIVE,, #01-114, SINGAPORE

575708

Singapore 575708

0.00

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU1036A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	486.50 FL	*- FL
2	1		*N/S REAR BUMPER SIDE RETAINER	Serviceable	120.00 FL	*- FL
3	8		*REAR BUMPER CLIPS	Not Necessary	40.00 FL	*- FL
4	1		*N/S REAR FENDER INNER SHIELD	Serviceable	52.80 FL	*- FL
5	4		*N/S REAR FENDER INNER SHIELD CLIPS	Not Necessary	20.00 FL	*- FL
6	1		*N/S REAR SPORT RIM (ORIGINAL)	Dented	1,645.50 FL	*1,645.50 FL
7	1		*N/S REAR WHEEL HUB	Serviceable	670.00 FL	*-FL
8	1		*N/S REAR WHEEL HUB BEARING }		0.00 FL	*- FL
9	1		*N/S REAR SHOCK ABSORBER	Serviceable	200.00 FL	*- FL
10	1		*N/S REAR TYRE	Serviceable	180.00 FS	*- FS
F=Fra	ınchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	3,414.80	1,645.50
			- List Item Discount on L Item	s 25.00/25.00% (S\$)	808.70	411.38
				Total Parts (S\$)	2,606.10	1,234.12
			Report was unsubmitted during this	s print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO DISMANTLE AND CHECK REAR UNDERCARRIAGE TO REPLACE AFFECTED PORTIONS	New	180.00	0.00
2	TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	80.00	60.00
3	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS	New	450.00	180.00
4	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	450.00	220.00
	Gross Labou	r Cost (S\$)	1,160.00	460.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >