

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007333/UGA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100502910
Claimant Vehicle No :	SMD754H	Insured Vehicle No :	SJX663S
Date of Loss:	02/07/2021	Nature of Claim:	TP
		Claim No:	4119601589SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD754H	Engine No:	D4FDJH551770
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7205703
Reg. Date:	31/07/2018 (Man. Year: 2018)	Odometer:	210781 km
Colour:	Red		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,043.00	1,244.70	1,798.30	59.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	970.00	290.00	23.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,303.00	2,214.70	2,088.30	48.53
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	4,303.00	1,750.00	2,553.00	59.33
+ GST 7.00/7.00% (S\$)	301.21	122.50	178.71	59.33
Nett Amount (S\$)	4,604.21	1,872.50	2,731.71	59.33
+ Car Rental (4.0 x S\$77.00/day) (S\$)		308.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,182.50		
Global Sum Settlement (S\$)		2,150.00		

INSPECTION

Date of Assignment:	19/07/2021		
Date Inspected:	19/07/2021	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	549.00 F	*549.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	28.00 F	*28.00 FL
3	1		*REAR BUMPER CENTRE PAD	Grazed	189.00 F	*189.00 FL
4	1		*REAR BUMPER LOWER	Repair	179.00 F	*- FL
5	1		*REAR BUMPER REVERSE SENSOR	O/S Shorted	320.00 F	*160.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.00 F	*- FL
7	1		*REAR BUMPER REFLECTOR	O/S Cracked	232.00 F	*116.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	367.00 F	*341.00 FL
9	2		*REAR BUMPER BRACKET	Not Necessary	168.00 F	*- FL
10	3		*REAR BUMPER LOWER BRACKET	Not Necessary	81.00 F	*- FL
11	1		*REAR BUMPER TOP BRACKET	Not Necessary	25.00 F	*- FL
12	1		*TAILGATE LID WEATHERSTRIP	Not Necessary	115.00 F	*- FL
13	1		*REAR END PANEL	Repair	611.00 F	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	123.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,043.00	1,383.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	138.30
Total Parts (\$\$)	3,043.00	1,244.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	500.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	650.00	400.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	50.00	50.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
Gross Labour Cost (\$)			1,260.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >