

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007335/BGS3Q2**Date:** 18/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800000230
Claimant Vehicle No :	SMK1610X	Insured Vehicle No :	SKS7194Y
Date of Loss:	01/07/2021	Nature of Claim:	TP
		Claim No:	8087566938SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK1610X	Engine No:	2NRX433195
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	MR2B23F3501171464
Reg. Date:	29/03/2019 (Man. Year: 2019)	Odometer:	109875 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,854.64	4,134.88	1,719.76	29.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,840.00	1,500.00	44.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,194.64	5,974.88	3,219.76	35.02
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	9,194.64	5,000.00	4,194.64	45.62
+ GST 7.00/7.00% (S\$)	643.62	350.00	293.62	45.62
Nett Amount (S\$)	9,838.26	5,350.00	4,488.26	45.62
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
Nett Liability (S\$)		5,890.00		

INSPECTION

Date of Assignment:	05/07/2021	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	06/07/2021 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	871.25 FL	*657.00 FL
2	1		*REAR BOOT LOGO	Necessary	81.70 FL	*65.90 FL
3	1		*REAR BOOT EMBLEM -VIOS	Necessary	78.10 FL	*78.10 FL
4	1		*REAR BOOT EMBLEM -G	Necessary	50.20 FL	*50.20 FL
5	1		*REAR BOOT LOCK	Jammed	211.40 FL	*211.40 FL
6	2		*REAR BOOT HINGE L+R	Not Damaged	277.40 FL	*- FL
7	1		*REAR BOOT W/STRIP	Cut	191.40 FL	*191.40 FL
8	1		*REAR BOOT CHROME HANDLE	No such part	384.72 FL	*- FL
9	1		*REAR BUMPER	Broken	684.45 FL	*684.45 FL
10	2		*REAR BUMPER RETAINER -L+R	Necessary	183.60 FL	*112.00 FL
11	1		*REAR BUMPER BRACKET L+R	N/S Broken	188.20 FL	*90.10 FL
12	1		*REAR BUMPER REFLECTOR L+R	N/S Missing	199.40 FL	*56.20 FL
13	5		*REAR BUMPER CLIP	Necessary	45.00 FL	*30.00 FL
14	1		*SET REVERSE SENSOR	Scratched	498.20 FL	*200.00 FL
15	1		*SET REVERSE SENSOR BRACKET	Necessary	24.60 FL	*24.60 FL
16	1		*TAIL LAMP L/H	Broken	575.40 FL	*575.40 FL
17	1		*TAIL LAMP PANEL L/H	Dented	362.60 FL	*362.60 FL
18	1		*TAIL LAMP CLIP L/H	Necessary	8.00 FL	*8.00 FL
19	1		*REAR FENDER RH	Bent	788.90 FL	*788.90 FL
20	1		*REAR FENDER COWLING LH	Not Damaged	94.20 FL	*- FL
21	6		*REAR FENDER COWLING CLIP LH	Not Necessary	24.00 FL	*- FL
22	1		*REAR FENDER INNER TRIM LH	Torn	280.93 FL	*280.93 FL
23	5		*REAR FENDER INNER TRIM CLIP LH	Necessary	25.00 FL	*25.00 FL
24	1		*REAR W/S GLASS MOULDING	Necessary	112.00 FL	*112.00 FL
25	1		*REAR END PANEL	Dented	894.30 FL	*616.00 FL
26	1		*REAR END PANEL TOP GARNISH	Broken	289.90 FL	*165.00 FL
27	2		*REAR END PANEL TOP GARNISH CLIP	Necessary	8.00 FL	*8.00 FL
28	1		*REAR W/S GLASS SEALANT	Necessary	80.00 FS	*30.00 FS
29	1		*REAR FENDER SEALANT LH	Necessary	100.00 FS	*30.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,712.85	5,483.18
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,858.21	1,348.30
Total Parts (\$\$)	5,854.64	4,134.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R & R ACCIDENT DAMAGE PARTS TO CUT/WELD ,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,400.00	800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	800.00
3	TO RUST PROOF ACCIDENT AFFECTED	New	120.00	30.00
4	TO R&R REAR BOOT MECHANISM	New	100.00	30.00
5	TO R&R REAR W/S GLASS	New	140.00	120.00
6	TO R&R REAR LUGGAGE COMPARTMENT	New	100.00	0.00
7	TO R&R REVERSE SENSOR AND CHECK FUNCTION	New	100.00	60.00
8	TO R&R UPHOLSTERY GARNISH AND ATTACHMENT PARTS	New	180.00	0.00
Gross Labour Cost (\$\$)			3,340.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >