

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21007348/EQF3E2

**Date:** 16/07/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070177573  
Claimant Vehicle No : SBS3077K Insured Vehicle No : SKS1414C  
Date of Loss: 02/07/2021 Nature of Claim: TP Claim No: 2903664600SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS3077K**  
Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9185567  
Reg. Date: 30/03/2012 (Man. Year: 2011) Chassis No: YV3S4P929CA153924  
Colour: Multi-colour Odometer: 665472 km  
Engine Capacity: 9364 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)  
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4/4 mm  
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4/4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,424.20	3,424.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,526.20	1,526.20	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,950.40</b>	<b>4,950.40</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>346.53</b>	<b>346.53</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>5,296.93</b>	<b>5,296.93</b>	<b>0.00</b>	<b>0.00</b>

### INSPECTION

Date of Assignment: 06/07/2021  
Date Inspected: 06/07/2021 Inspected At: SBS Transit Ltd (Soon Lee Road)  
28 Soon Lee Road  
Singapore 628083  
Estimated Period of Repair: 2.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PANEL ATTACHMENT BRKT;SHEETMETAL	Necessary	39.00 F	*39.00 F
2	1		*SIDE SHEETMETAL PANEL	Dented	1,043.90 F	*1,043.90 F
3	2		*PANEL ATTACHMENT BRKT;SHEETMETAL	Dented	80.60 F	*80.60 F
4	1		*STUD PILLAR;40X40MM;N/S FRAME	Bent	53.30 F	*53.30 F
5	1		*SIDE SHEETMETAL PANEL	Dented	998.40 F	*998.40 F
6	1		*4 BOLT CORNER ASSY;RR FRAME	Necessary	19.50 F	*19.50 F
7	1		*SIDE SHEETMETAL PANEL	Dented	943.80 F	*943.80 F
8	5		*M8X16 ALLEN HEAD BOLT PATCHED	Necessary	53.30 F	*53.30 F
9	1		*PILLAR TRIM INFILL	Torn	192.40 F	*192.40 F
F=Franchise part.						
					<b>Total Parts (S\$)</b>	<b>3,424.20      3,424.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR }	New	1,526.20	1,526.20
2	VINYL }	New	0.00	0.00
3	SPRAY PAINTING (NPA)	New	0.00	0.00
4	ADVERTISEMENT (NPA)	New	0.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,526.20</b>	<b>1,526.20</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >