

ASS. REC. BY:

Steel 7 CS/A1421007348/Eqf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

At Workshop m/s

of

Insured:

Policy No.

Claims No.

2903664600SG

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

SIA / PR Sent

Consistent? : Yes or No

Est. Repair:

2

days

Res.:

Yes or No

Cum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBS 3977K

Yr Regn: 30/03/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo B97LE

c.e. 9364

Colour:

White - Silver

A/C: Insured / Std / Nil / N

Sp. Reading

165472

T/Radio: Insured / Std / Nil / N

Eng/No:

C/No:

VV354P:929CA153924

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brakes: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R17.5

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

U/Bal.

4

mm

U/Bal.

4

mm

D.O.A.

2/7/21

D.O.A.

6/7/21

Survey held at

SBS (Som Kee Road)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or

Rear LH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Waiting estimate

13/07/21 Submit final fig \$4950.40 (repair cost not conclude)

Date/Time, File, Poss. to?



Prell. Report

13/07 Typist



Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photo:

Others:

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Inve (\$



Weld and (\$

Approved by:

MER-TP

Date/Time, File, Return to?