



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 8721R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH	DENTED	950.00	950.00
1	SET FRONT DOOR STICKER RH	NECESSARY	56.90	56.90
1	FRONT DOOR LOCK RH	NOT NECESSARY	262.30	-
1	FRONT DOOR GLASS REGULATOR RH (NPA)	NOT NECESSARY	-	-
1	FRONT DOOR WEATHERSTRIP RH	NOT NECESSARY	110.80	-
1	FRONT DOOR INNER TRIM RH (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-276.00	-201.38
			1,104.00	805.52
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT DOOR VISOR (SN)	NOT NECESSARY	180.00	-
			180.00	-
	<u>LABOUR</u>			
	TO KNOCK & STRAIGHTEN CENTER PILLAR RH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS REALIGN ALL CONNECTION. }		300.00	120.00
	REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM. }		60.00	-
	SPRAY PAINT CENTER PILLAR RH AND FRONT DOOR RH.		350.00	200.00
	RUST PROOF AFFECTED AREAS.		30.00	30.00
			740.00	350.00
	GRAND TOTAL		2,024.00	1,155.52
	RECOMMENDED COST OF REPAIRS			1,155.52

Report Ref No. CS/SMO21007350/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.