



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 8805R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	50.00
1	BACK SENSOR GREY METALLIC (SN)	BROKEN	146.70	146.70
1	LAMP ASSY, RR COMBIN (SN)	BROKEN	323.00	323.00
1	LAMP ASSY, RR COMBIN (SN)	BROKEN	323.00	323.00
1	LAMP ASSY, RR, RH (SN)	NOT NECESSARY	191.30	-
1	LAMP ASSY, RR, LH (SN)	NOT NECESSARY	191.30	-
1	COVER, RR BUMPER, L (SN)	DENTED	526.00	526.00
4	PIECE, RR BUMPER (SN)	NECESSARY	16.40	16.40
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	121.30	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	121.30	-
1	REINFORCEMENT SUB-AS (SN)	DENTED	336.30	336.30
1	PANEL SUB-ASSY, BODY (SN)	DENTED	722.50	722.50
1	PLATE, RR FLOOR FINI (SN)	NOT NECESSARY	244.30	-
2	CLIP (SN)	NECESSARY	5.00	5.00
1	PANEL SUB-ASSY, LUGG (SN)	DENTED	798.90	798.90
1	WEATHERSTRIP, LUGGAG (SN)	TORN	177.60	177.60
1	LOCK ASSY, LUGGAGE C (SN)	NOT NECESSARY	95.00	-
1	PLATE, LUGGAGE COMPT (SN)	NECESSARY	46.00	46.00
1	EMBLEM, SYMBOL (SN)	NECESSARY	53.70	53.70
1	PLATE, LUGGAGE COMPT (SN)	NECESSARY	35.90	35.90
			4,525.50	3,561.00
<u>LABOUR</u>				
TO RESET ECU AND REPROGRAMME.			180.00	180.00
SUPPLY SEALANT (NETT) FOR REAR END PANEL AND REAR BOOTLID.			120.00	100.00
TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.			122.40	122.40
R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.			180.00	180.00
R/I REAR CARPET, TRIMMING, REAR CAMERA AND OTHER ATTACHMENT TO FACILIATE REPAIRS.		NOT NECESSARY	360.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS. TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.		4,320.00	2,880.00
			3,540.00	1,770.00
			8,822.40	5,232.40
GRAND TOTAL			13,347.90	8,793.40
RECOMMENDED COST OF REPAIRS				8,793.40

Report Ref No. CS/SMR21007351/Euf3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.