



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2108378

INV Date 06/12/2021

Reference CC4/LPC21007353/Epa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMN 2119B
Insured Veh. YP 2428G
Claim No. 21/21/21/VC05/024705
Policy No. Z21VC05007475
Accident Date 26/06/2021
Inspection Date 12/07/2021

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21007353/Epa3q2 Date: 06/12/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 2428G	Veh. Inspected	SMN 2119B	
Policy No.	Z21VC05007475	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/024705	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	06/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JM6GL1072K0313005	Colour	BLUE	
Odometer	40432 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	4 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	4 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	4 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2021	Inspection Date	12/07/2021	
Survey held at	27A Tanjong Penjuru Singapore 609042			
Repairer	TRANS EUROKARS PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 2119B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP RH	CUT	4,759.30	4,759.30
1	TAPE SEAL HEADLAMP RH	NECESSARY	102.00	102.00
1	RIVET	NECESSARY	3.50	3.50
1	BRACKET 'A' HEADLAMP RH	NOT NECESSARY	30.80	-
1	BRACKET 'B' HEADLAMP RH	NOT NECESSARY	15.50	-
1	SIDE MIRROR RH	BROKEN	475.90	475.90
1	HOUSING SIDE MIRROR RH	CUT	111.00	111.00
1	SIGNAL TURN LAMP RH	NOT NECESSARY	85.80	-
1	GLASS & HOLDER RH	NOT NECESSARY	282.50	-
1	FRONT FENDER RH	DENTED	383.70	383.70
10	FASTENER @\$3.00	NECESSARY	30.00	30.00
1	FRT BUMPER	TO REPAIR SEE LABOUR	1,211.90	-
1	GROMMET SCREW	NECESSARY	2.90	2.90
1	CHROME COVER FOG LAMP	NOT NECESSARY	65.80	-
1	COVER FOG LAMP	NOT NECESSARY	20.50	-
1	RETAINER RH FRONT BUMPER	NOT NECESSARY	17.10	-
4	RIVET @\$4.50	NECESSARY	18.00	18.00
4	RIVET ,SPLASH SHIELD	NOT NECESSARY	16.00	-
1	CHROME MOULD OUTER FRONT DOOR RH	DENTED	96.00	96.00
9	FASTENER @\$7.20	NOT NECESSARY	64.80	-
	LESS 20% DISCOUNT		-1,558.60	-1,196.46
			6,234.40	4,785.84
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
			50.00	30.00
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER AND FRONT FENDER RH .TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.INCLUSIVE OF THE REPAIR OF FRT BUMPER .		1,650.00	990.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY FRONT BUMPER ,FRONT FENDER RH,FRONT DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENTS.		2,520.00	1,360.00
	TO TRANSFER FRONT PEDESTRIAN SENSORS.		330.00	330.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		180.00	180.00
			4,830.00	3,010.00
GRAND TOTAL			11,114.40	7,825.84
RECOMMENDED COST OF REPAIRS				7,825.84

Report Ref No. CC4/LPC21007353/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 2119B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

