

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007354/AGS3Q2
Date: 03/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070140674
Claimant Vehicle No :	SMK9843M	Insured Vehicle No :	SKT6001Y
Date of Loss:	01/07/2021	Nature of Claim:	TP
		Claim No:	3787490056SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9843M		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD218487
Reg. Date:	27/01/2016 (Man. Year: 2015)	Chassis No:	WAUZZZ8U4GR045910
Colour:	Blue	Odometer:	70120 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R17	Rear Tyre Size:	235/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,925.00	3,693.44	4,231.56	53.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,952.00	3,022.00	2,930.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,877.00	6,715.44	7,161.56	51.61
+ GST 7.00/7.00% (S\$)	971.39	470.08	501.31	51.61

Nett Amount (S\$)	14,848.39	7,185.52	7,662.87	51.61
		+ Loss of Use (4.0 x S\$50.00/day) (S\$)	200.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	7,387.52	

INSPECTION

Date of Assignment: 02/07/2021

Date Inspected: 02/07/2021

Estimated Period of Repair: 4.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,580.00 FS	*1,264.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	124.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	880.00 FS	*704.00 FS
4	1		*REAR BUMPER DIFFUSER	Deformed	706.00 FS	*564.40 FS
5	1		*TOWING EYE COVER -LH	Deformed	43.00 FS	*34.08 FS
6	1		*TOWING EYE COVER -RH	Not Necessary	26.00 FS	*- FS
7	1		*REAR BUMPER TAIL LIGHT -LH	Not Necessary	457.00 FS	*- FS
8	1		*REAR BUMPER TAIL LIGHT -RH	Not Necessary	457.00 FS	*- FS
9	1		*REAR BUMPER CARRIER	Not Necessary	651.00 FS	*- FS
10	6		*HEX COLLARD BOLT	Not Necessary	30.00 FS	*- FS
11	2		*REAR BUMPER SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
12	4		*REAR BUMPER SEAL RING	Not Necessary	6.00 FS	*- FS
13	1		*PACKING ADHESIVE	Necessary	19.00 FS	*14.88 FS
14	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
15	1		*Q3 EMBLEM	Necessary	99.00 FS	*79.04 FS
16	1		*TFSI EMBLEM	Necessary	99.00 FS	*79.04 FS
17	2		*REAR WHEEL ARCH -LH/RH	Necessary	1,056.00 FS	*844.00 FS
18	1		*REAR SILENCER	Not Necessary	1,088.00 FS	*- FS
19	1		*REAR SILENCER DUAL CLIP	Not Necessary	59.00 FS	*- FS
20	1		*REAR SILENCER RETAINING CLIP CENTRE	Not Necessary	17.00 FS	*- FS
21	1		*REAR SILENCER RETAINING CLIP -RH	Not Necessary	17.00 FS	*- FS
22	1		*REAR SILENCER RETAINING BRACKET -LH	Not Necessary	73.00 FS	*- FS
23	1		*TRIM SET EXHAUST TAILPIPES (NPA)	Not Necessary	0.00 FS	*- FS
24	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,925.00	3,693.44
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER ,REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER ,REAR LOWER SPOILER ,REAR LID AND BOTH REAR WHELL ARCH TRIMS	New	3,800.00	2,050.00
4	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,952.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >