

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21007357/TEA3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_01

**Claimant Vehicle No :** FBS291C **Insured Vehicle No :** GBK1996M

Date of Loss: 02/07/2021 Nature of Claim: TP Claim No: MFL2021D0002807

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS291C**  
 Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS Engine No: G3J1E0554011  
 Reg. Date: 23/12/2020 (Man. Year: 2020) Chassis No: MH3SG4620LJ078573  
 Colour: White Odometer: 7983 km  
 Engine Capacity: 155 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R14 Rear Tyre Size: 140/70 R14  
 Front Left Side: MITAS 6 mm Rear Left Side: MITAS 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,066.40	2,066.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	250.00	100.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>2,416.40</b>	<b>2,316.40</b>	<b>100.00</b>	<b>4.14</b>
<b>+ Loss of Use (5.0 x S\$30.00/day) (S\$)</b>		150.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,473.85</b>		

INSPECTION

Date of Assignment: 05/07/2021

Date Inspected: 06/07/2021 Inspected At:

Teo Spray Painting (HQ)  
 BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558  
 Singapore 539187

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Jan 2022)	
<b>Parts:</b>	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBS291C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	78.00 FL	*78.00 FL
2	1		*LEFT SIDE MIRROR	Cut	25.00 FL	*25.00 FL
3	1		*RIGHT SIDE MIRROR	Cut	25.00 FL	*25.00 FL
4	1		*SET BALANCER	Cut	50.00 FL	*50.00 FL
5	1		*STEERING CONE	Necessary	90.00 FL	*90.00 FL
6	1		*FRONT BRAKE LEVER	Cut	28.00 FL	*28.00 FL
7	1		*UNDER BRACKET	Bent	280.00 FL	*280.00 FL
8	1		*SET FORK	Bent	300.00 FL	*300.00 FL
9	1		*FRONT SIGNAL LEFT SIDE	Cracked	45.00 FL	*45.00 FL
10	1		*HEAD LAMP	Cut	380.00 FL	*380.00 FL
11	1		*LEFT FRONT SIDE COVER	Cut	35.00 FL	*35.00 FL
12	1		*RIGHT FRONT SIDE COVER	Cut	35.00 FL	*35.00 FL
13	1		*LEFT FRONT SIDE BLACK COVER	Cracked	48.00 FL	*48.00 FL
14	1		*RGHT FRONT SIDE BLACK COVER	Cut	48.00 FL	*48.00 FL
15	1		*INNER LEFT FRONT SIDE BLACK COVER	Cracked	48.00 FL	*48.00 FL
16	1		*INNER RIGHT FRONT SIDE BLACK COVER	Deformed	48.00 FL	*48.00 FL
17	1		*RIGHT TOP STEP COVER	Cracked	45.00 FL	*45.00 FL
18	1		*RIGHT SIDE LOWER BLACK COVER	Cut	45.00 FL	*45.00 FL
19	1		*RADIATOR COVER	Cut	35.00 FL	*35.00 FL
20	1		*EXHAUST PROTECTOR	Cut	55.00 FL	*55.00 FL
21	1		*MAIN STAND	Dented	75.00 FL	*75.00 FL
22	1		*RIGHT REAR FOOTREST	Cut	65.00 FL	*65.00 FL
23	1		*RIGHT SIDE BLACK COVER	Cut	30.00 FL	*30.00 FL
24	1		*TOP BOX	Cut	200.00 FL	*200.00 FL
25	1		*LEFT TAIL COVER	Cracked	58.00 FL	*58.00 FL
26	1		*METER COVER	Cracked	45.00 FL	*45.00 FL
27	1		*FRONT WHEEL SHAFT	Bent	25.00 FL	*25.00 FL
28	1		*LAMP STAY	Bent	55.00 FL	*55.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,296.00</b>	<b>2,296.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	229.60	229.60
<b>Total Parts (\$)</b>	<b>2,066.40</b>	<b>2,066.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	280.00	200.00
2	TRANSPORT	New	70.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>350.00</b>	<b>250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >