

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21007359/EQF3E2

Date: 15/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBK5575T

Insured Vehicle No : SMA603B

Date of Loss: 17/06/2021

Nature of Claim: TP

Claim No: 1645763836SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK5575T**

Make & Model: YAMAHA CZD300A / XMAX300, 292cc

Engine No: H336E0081176

Reg. Date: 27/06/2020 (Man. Year: 2020)

Chassis No: MH3SH0842LK010919

Colour: Blue

Odometer: 0 km

Engine Capacity: 292 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-15

Rear Tyre Size: 140/70-14

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/07/2021

Date Inspected: 06/07/2021

Inspected At:

Hup Hin (HQ)

Blk 1006 Bt Merah Lane 2, #01-02

Singapore 159762

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$17,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK GARNISH	Cut	0.00 F	*- F
3	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
4	1		*FRONT HEADLAMP GARNISH	Cut	0.00 F	*- F
5	1		*FRONT WINDSHIELD GARNISH	Cut	0.00 F	*- F
6	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
7	1		*FRONT RH SIGNAL LAMP	Missing	0.00 F	*- F
8	1		*HANDLE BAR	Bent	0.00 F	*- F
9	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
10	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
11	2		*SIDE FAIRING	Broken	0.00 F	*- F
12	1		*REAR FAIRING	Cut	0.00 F	*- F
13	1		*FAIRING LOWER	Broken	0.00 F	*- F
14	1		*RADIATOR	Dented	0.00 F	*- F
15	1		*RADIATOR COWLING	Broken	0.00 F	*- F
16	1		*REAR FOOT REST	Cut	0.00 F	*- F
17	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
18	1		*REAR BOX	Cut	0.00 F	*- F
19	1		*REAR BOX BRACKET	Cut	0.00 F	*- F
20	1		*EMBLEM	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >