

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007360/AVCN2**Date:** 17/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00069252101
Claimant Vehicle No :	SMD7390C	Insured Vehicle No :	GN6288R
Date of Loss:	03/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D203732/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7390C	Engine No:	PE21176358
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GL1072K0303472
Reg. Date:	31/08/2018 (Man. Year: 2018)	Odometer:	36475 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,607.60	4,163.60	444.00	9.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	730.00	1,270.00	63.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,607.60	4,893.60	1,714.00	25.94
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	6,607.60	3,900.00	2,707.60	40.98

INSPECTION

Date of Assignment:	06/07/2021		
Date Inspected:	07/07/2021	Inspected At:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21 Singapore 415875
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7390C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,212.00 FL	*1,212.00 FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	38.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	18.00 FL	*- FL
4	1		*FRONT BUMPER TOP GARNISH COVER	Deformed	421.00 FL	*421.00 FL
5	1		*FRONT BUMPER REFLECTOR	Not Necessary	252.00 FL	*- FL
6	1		*RH HEAD LAMP	Cut	3,206.00 FL	*3,206.00 FL
7	1		*HEAD LAMP BRACKET	Not Necessary	38.00 FL	*- FL
8	1		*FRONT BUMPER GRILLE CHROME	Cracked	252.00 FL	*252.00 FL
9	1		*FRONT LOWER GRILLE BASE	Not Necessary	134.00 FL	*- FL
10	10		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
11	8		*FRONT FENDER RH INNER SPLASH GUARD CLIPS	Not Necessary	40.00 FS	*- FS
12	1		*FRT GRILL INNER BRACKET RH	Cracked	38.00 FL	*38.00 FL
13	1		*HEAD LAMP LOWER BRACKET RH	Cracked	38.00 FL	*38.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,737.00	5,197.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,129.40	1,033.40
Total Parts (\$\$)	4,607.60	4,163.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CUT OUT DAMAGE PARTS,ALIGN,PANEL BEATING AND RENEW REPLACE PARTS	New	800.00	350.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	800.00	350.00
3	TO REWIRE FRONT PORTION AND REFOCUS HEADLAMP	New	50.00	30.00
4	TO REMOVE AND REPLACE DAMAGED FRONT UNDERCARRIAGE	New	250.00	0.00
5	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			2,000.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >