

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21007362/BVCE2

Date: 30/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00092932000
Claimant Vehicle No : FBG2610R Insured Vehicle No : GBG1816X
Date of Loss: 03/07/2021 Nature of Claim: TP Claim No: SNM21D203721/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBG2610R**
Make & Model: YAMAHA T135, 135cc Engine No: 5YP303632
Reg. Date: 10/05/2012 (Man. Year: 2012) Chassis No: 5YP303632
Colour: White Odometer: 69005 km
Engine Capacity: 135 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/80/17 Rear Tyre Size: 90/80/17
Front Left Side: Dunlop 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,827.24	1,275.94	4,551.30	78.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	550.00	670.00	54.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,047.24	1,825.94	5,221.30	74.09
Approved Total (Overridden) (\$\$)		1,400.00		
(\$\$)	7,047.24	1,400.00	5,647.24	80.13
+ GST 7.00/7.00% (\$\$)	493.31	98.00	395.31	80.13
Nett Amount (\$\$)	7,540.55	1,498.00	6,042.55	80.13

INSPECTION

Date of Assignment: 06/07/2021
Date Inspected: 06/07/2021 Inspected At: Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Singapore 415875
Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Nov 2021)	
Parts:	N/A	YAMAHA T135 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG2610R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR RH	Bent	155.00 FL	*155.00 FL
2	1		*SET HANDLE BAR GRIP	Cut	84.60 FL	*15.00 FL
3	1		*SET BALANCER	No such part	55.70 FL	*- FL
4	1		*SET MIRROR ASSY	Cut	85.40 FL	*85.40 FL
5	2		*BRAKE CLUTCH LEVER	Cut	149.60 FL	*42.00 FL
6	1		*HEADLAMP COWLIG	Cut	131.20 FL	*131.20 FL
7	1		*CLUTCH CABLE	Not Necessary	78.50 FL	*- FL
8	1		*BRAKE CABLE	Not Necessary	78.70 FL	*- FL
9	1		*FRONT CENTER COWLING	Not Damaged	142.60 FL	*- FL
10	1		*EMBLEM FRONT, R/H	Necessary	54.80 FL	*24.00 FL
11	1		*FRONT FENDER	Cut	144.10 FL	*105.00 FL
12	1		*SET FORK ASSY L+R	Bent	657.20 FL	*390.00 FL
13	1		*FORK STEM	Necessary	125.70 FL	*90.00 FL
14	1		*BRAKE DISC	Not Damaged	149.70 FL	*- FL
15	1		*BRAKE CALIPER	Not Damaged	98.40 FL	*- FL
16	2		*FRONT SIDE FAIRING RL	Not Damaged	314.80 FL	*- FL
17	1		*RIDER FOOT REST RH	Cut	125.90 FL	*55.00 FL
18	1		*PILLION FOOT REST	Not Damaged	139.70 FL	*- FL
19	1		*ENGINE COVER	Not Damaged	145.70 FL	*- FL
20	1		*REAR SIDE FAIRING RL	Not Damaged	137.40 FL	*- FL
21	1		*EXHAUST ASSY	Not Necessary	747.40 FL	*- FL
22	1		*EXHAUST GASKET	Not Necessary	138.50 FL	*- FL
23	1		*EXHAUST GUARD	Cut	54.00 FL	*54.00 FL
24	1		*BRAKE PEDAL	Cut	158.30 FL	*60.00 FL
25	1		*BRAKE PEDAL BRACKET	Not Damaged	137.10 FL	*- FL
26	1		*RADIATOR	Not Damaged	327.50 FL	*- FL
27	1		*RADIATOR BRACKET	Not Damaged	115.40 FL	*- FL
28	1		*CENTER COWLING RL	Not Damaged	158.40 FL	*- FL
29	1		*SWING ARM	Not Damaged	270.30 FL	*- FL
30	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
31	1		*REAR WHEEL	Not Damaged	280.00 FS	*- FS
32	1		*REAR WHEEL RIM	Not Damaged	320.00 FS	*- FS
33	1		*FORK OIL	Necessary	45.00 FS	*30.00 FS
34	1		*BOX	Cut	280.00 FS	*120.00 FS
35	1		*BOX BRACKET	Not Necessary	146.80 FS	*- FS
36	1		*STICKERS	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,343.40	1,396.60
- List Item Discount on L Items 10.00/10.00% (\$)	516.16	120.66
Total Parts (\$)	5,827.24	1,275.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	600.00	300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	400.00	200.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	80.00	0.00
4	TO REBLEED BRAKE SYSTEM	New	60.00	20.00
5	ELECTRICAL	New	80.00	30.00
Gross Labour Cost (\$)			1,220.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >