#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd. Our File No: CS/CTI21007366/R1UCE2 3 Anson Road, #16-00 Springleaf Tower

Date: 27/07/2021 Singapore 079909

**REFERENCE** 

Insured/Claimant: LTD. TECK LEE MACHINERY PTE.

Policy No: DMCVSNA00068142002

Nature of Claim 03/07/2021 OD SNM21D203738/C01/THAMYL Date of Loss: Claim: No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

GX6151Z Reg No:

Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D054592 Reg. Date: 11/08/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0101019

Colour: Odometer: 0 kmGrey

**Engine Capacity:** 1461 cc Market Value/New Car Price: S\$34.000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** Nο Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 175/70R14C Rear Tyre Size: 175/70R14C Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gross	Total (S\$)	0.00	0.00	0.00	
- Ex	xcess (S\$)	0.00	450.00	-450.00	
Nett Amount (S\$)		0.00	-450.00	450.00	

**INSPECTION** 

Date of Assignment: 06/07/2021 Present Location: Goldbell Engineering Pte Ltd (Tuas)

Goldbell Engineering Pte Ltd (Tuas)

Date Inspected: 07/07/2021 Inspected At: 10 Tuas Ave 18

Singapore 638894

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL Tan Hui Zhen Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### TOTAL LOSS ASPECT

Market Value: \$34,000.00 OMV: \$20,122.00

PARF Rebate (1): \$0

Quota Premium Paid : \$42,169.00 COE Rebate (2) : \$17,241.00 Total Rebate (1) + (2) = : \$17,241.00

The total amount incurred will be Market Value \$34,000.00 minus Total Rebate \$17,241.00 = \$16,759.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

### **REPAIR DETAILS**

#### Reference

Part Source: (Last Synchronised: 16 Jul 2021)

Parts: N/A NISSAN NV200 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GX6151Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*BADLY BURNED VEHICLE		0.00 F	*-F
F=Franchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >