



Your Ref : SNM21D203738/C01/THAMYL

Date: 27th July 2021

Our Ref : CS/CTI21007366/R1uce2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GX 6151Z
ACCIDENT ON 03/07/2021**

Instruction was received to inspect the vehicle Reg. No. GX 6151Z. The inspection was conducted on 07/07/2021 at the premises of M/s Goldbell Engineering Pte Ltd, 10 Tuas Ave 18, Singapore 638894.

The following vehicle information was recorded:

Registration Number	: GX 6151Z
Make/Model	: Nissan NV200 1.5L MT ABS Airbag 2WD 6DR Euro 5
Year of Registration	: 2015
Body Colour	: Grey
Chassis Number	: VSKYBAM20Z0101019
Engine Capacity	: 1461 cc

The vehicle caught fire. The cause of fire probably due to electrical at the engine compartment. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 34,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 17,241.00)
Nett Liability	<u>S\$ 16,759.00</u> =====

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.