



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107285

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/10/2021
Reference CC6/CTI21007368/Urs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 7207P
Insured Veh. GBF 8700E
Claim No. SNM21D203763/LKKDS
Policy No. DMCVSNA00031592103
Accident Date 02/07/2021
Inspection Date 06/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21007368/Urs3q2 Date: 20/10/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 8700E	Veh. Inspected	GBG 7207P	
Policy No.	DMCVSNA00031592103	Coverage (\$)	0.00	
Claim No.	SNM21D203763/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	06/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2015026664	Colour	WHITE	
Odometer	75117 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	6 mm	
L/H Front Tyre	195 R15	MICHELIN	6 mm	
R/H Rear Tyre	195 R15	MICHELIN	6 mm	
L/H Rear Tyre	195 R15	MICHELIN	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	02/07/2021	Inspection Date	06/07/2021	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7207P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN	SHATTERED	1,150.95	900.10
1	REAR GATE	BADLY DENTED	2,162.70	2,150.70
1	REAR GATE LOGO	NOT NECESSARY	80.10	-
1	REAR GATE INNER TRIM	NOT NECESSARY	550.35	-
1	REAR GATE RUBBER	NOT NECESSARY	405.45	-
1	REAR WIPER ARM	NOT NECESSARY	180.10	-
1	REAR WIPER BLADE	NOT NECESSARY	85.30	-
1	REAR WIPER ARM COVER	NOT NECESSARY	35.30	-
1	REAR WIPER BLADE MOTOR	NOT NECESSARY	549.00	-
	LESS 25% DISCOUNT		-1,299.81	-762.70
			3,899.44	2,288.10
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SPONGE (SN)	NECESSARY	30.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR GATE STICKER '70KM/H' (SN)	NECESSARY	25.00	10.00
1	REAR GATE STICKER 'HIACE' (SN)	NECESSARY	25.00	25.00
1	REAR GATE STICKER '8 PAX' (SN)	NECESSARY	25.00	10.00
1	REAR GATE STICKER '1250KG' (SN)	NECESSARY	25.00	25.00
			210.00	140.00
	<u>LABOUR</u>			
	WIRE CHECKING .		30.00	20.00
	R/R REAR WINDSCREEN .		120.00	100.00
	TRANSFER REAR GATE PARTS .		100.00	60.00
	LABOUR .		300.00	100.00
	PAINTING .		250.00	200.00
			800.00	480.00
	GRAND TOTAL		4,909.44	2,908.10



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00
---	--	--	----------

Report Ref No. CC6/CTI21007368/Urs3q2

A handwritten signature in black ink, appearing to be 'Chua' followed by a stylized 'K' and 'S'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 7207P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 7207P

RE-INSPECTION

