

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5107L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FACE,FR BUMPER (SN)	CRUSHED	706.00	706.00
1	GARNISH,FR BUMPER,LH (SN)	NOT NECESSARY	127.00	-
1	BRACKET,FR BUMPER,LH (SN)	BROKEN	13.00	13.00
12	CLIP,FR BUMPER (SN)	NECESSARY	48.00	48.00
1	FENDER,FR LH (SN)	DENTED	500.00	500.00
1	SHIELD,FR WHEELHOUSE,LH (SN)	NOT NECESSARY	98.00	-
1	HEADLAMP ASSY,LH (SN)	BROKEN	663.00	663.00
1	EMBLEM ECO (SN)	NECESSARY	17.00	17.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	BODY PNL SEALANT (SN)	NOT NECESSARY	80.00	-
			2,302.00	1,967.00
	<u>LABOUR</u>			
	RENEW FRT BUMPER & LHF FENDER.		2,560.00	1,280.00
	RESPRAY FRT BUMPER & LHF FENDER.		1,650.00	1,100.00
	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM.		80.00	80.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		280.00	280.00
	SUPPLY FRT NUMBER PLATE WITH CASING.		80.00	50.00
	RE-SEAL WEEKEND PLATE.		120.00	120.00
	APPLY ANTI CORROSION ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	ACCIDENT TOWED FROM 464 UPPER SERANGOON TO C&C PG (ADDITIONAL).		85.00	85.00
			4,935.00	2,995.00
	GRAND TOTAL		7,237.00	4,962.00

RECOMMENDED COST OF REPAIRS			4,962.00
-----------------------------	--	--	----------

Report Ref No. CS/SMR21007374/Euf3n2

a de la companya della companya dell

CHEN TSUE YEE

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator