

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21007375/EQF3E2

Date: 08/10/2021

REFERENCE

Insured/Claimant:	WANG XIAOQING	Policy No:	1800089003		
Date of Loss:	06/07/2021	Nature of Claim:	OD	Claim No:	4863302754SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC9617S	Engine No:	10XTA40887797
Make & Model:	CITROEN C4, 1.6 PICASSO (A)	Chassis No:	VF73AHNYTHJ893702
Reg. Date:	30/07/2018 (Man. Year: 2017)	Odometer:	20113 km
Colour:	Beige		
Engine Capacity:	1199 cc		
Market Value/New Car Price:	S\$81,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,262.40	11,634.40	1,628.00	12.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,935.00	7,695.00	1,240.00	13.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,197.40	19,329.40	2,868.00	12.92
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	21,897.40	19,029.40	2,868.00	13.10
+ GST 7.00/7.00% (S\$)	1,532.82	1,332.06	200.76	13.10
Nett Amount (S\$)	23,430.22	20,361.46	3,068.76	13.10

INSPECTION

Date of Assignment: 06/07/2021

Date Inspected: 06/07/2021 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MAIN HARNESS (NPA)	Broken	0.00 FS	*- FS
2	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Broken	1,031.00 FL	*1,031.00 FL
4	1		*BUMPER BRACKET	Broken	330.00 FL	*330.00 FL
5	1		*BUMPER MOULDING	Missing	207.00 FL	*207.00 FL
6	1		*BUMPER MOULDING	Missing	207.00 FL	*207.00 FL
7	1		*BUMPER MOULDING	Missing	227.00 FL	*227.00 FL
8	1		*BMPR RUBBR BOOT	Not Necessary	276.00 FL	*- FL
9	1		*GUARD GRILLE INFERIEUR	Broken	311.00 FL	*311.00 FL
10	1		*BADGE SUPPORT	Broken	205.00 FL	*205.00 FL
11	1		*CHEVRON EMBLEM SUPERIEUR	Cut	161.00 FL	*161.00 FL
12	1		*SET BRACKET	Missing	125.00 FL	*125.00 FL
13	1		*BUMPER MOULDING	Not Necessary	173.00 FL	*- FL
14	1		*BRACKET SET LAT	Broken	125.00 FL	*125.00 FL
15	1		*SET ABSORBERS	Not Necessary	92.00 FL	*- FL
16	1		*BUMPER BRACKET	Not Necessary	516.00 FL	*- FL
17	1		*BUMPER BRACKET	Broken	194.00 FL	*194.00 FL
18	1		*PLUG LH	Broken	96.00 FL	*96.00 FL
19	1		*FACE CROSSMEMBER SUP	Broken	226.00 FL	*226.00 FL
20	1		*AIR BULKHEAD LH	Not Necessary	108.00 FL	*- FL
21	1		*AIR BULKHEAD	Cut	154.00 FL	*154.00 FL
22	1		*BRACKET CROSSME LH ASSY	Bent	196.00 FL	*196.00 FL
23	1		*FACING SUPPORT LH ASSY	Repair	201.00 FL	*- FL
24	1		*FRT MIN BPR FIX	Necessary	252.00 FL	*252.00 FL
25	1		*FRONT WING LH ASSY	Dented	571.00 FL	*571.00 FL
26	1		*WING INNER FRAM LH ENS	Repair	518.00 FL	*- FL
27	1		*MUDGUARD LH ASSY	Broken	194.00 FL	*194.00 FL
28	1		*ACCOUSTIC SEAL	Not Necessary	47.00 FL	*- FL
29	1		*ENGINE BONNET ASSY	Dented	1,042.00 FL	*1,042.00 FL
30	1		*BONNET HINGE LH	Bent	178.00 FL	*178.00 FL
31	1		*BONNET HINGE RH	Bent	178.00 FL	*178.00 FL
32	1		*SOUND PROOFING	Crushed	235.00 FL	*235.00 FL
33	1		*BONNET LOCK	Not Necessary	54.00 FL	*- FL
34	1		*LOCKING HOOK	Not Necessary	50.00 FL	*- FL
35	2		*BONNET BUFFER	Necessary	52.00 FL	*52.00 FL
36	1		*DEFLECTOR GLASS LH	Cut / Crushed	264.00 FL	*264.00 FL
37	1		*FRONT LIGHT LH	Missing	409.00 FL	*409.00 FL
38	1		*HEADLIGHT ASSY LH	Missing	718.00 FL	*718.00 FL
39	1		*FOG HEADLIGHT	Broken	128.00 FL	*128.00 FL
40	1		*GC4P 2018-BODY KIT	Broken	1,500.00 FS	*1,500.00 FS
41	1		*ALLOY WHEEL 7 J17 CH5-50 LHF	Cut	709.00 FL	*709.00 FL
42	1		*CHEVRON EMBLEM INFERIEUR	Cut	161.00 FL	*161.00 FL
43	1		*MAIN HARNESS	Broken	1,892.00 FL	*1,892.00 FL
			(Supplementary)			
44	2		*COOLING LIQUID DRUM 2L PAE - 35	Necessary	50.00 FL	*50.00 FL
			(Supplementary)			
45	1		*BATTRY FIAMM VR760 L3	Broken	250.00 FS	*250.00 FS
			(Supplementary)			
46	1		*COMPUTER	Broken	1,490.00 FL	*1,490.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,133.00	14,098.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,870.60	2,463.60
Total Parts (\$\$)	13,262.40	11,634.40

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT BUMPER BODY KIT, BONNET, LHF FENDER, LHF FENDER INNER PNL & FRT SUPPORT. REPAIR RH FENDER	New	3,000.00	2,500.00
2	RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, FRT SUPPORT, BONNET, LHF FENDER, LHF FENDER INNER PNL & RH FENDER	New	2,660.00	2,470.00
3	REMOVE & REFIX AIRCON CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	550.00	80.00
5	RENEW LHF SPORT RIM & TRANSFER TYRE / WHEEL BALANCE	New	50.00	50.00
6	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	50.00	50.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	225.00	225.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	180.00	180.00
9	SUPPLY FRONT NUMBER PLATE WITH CASING	New	60.00	60.00
10	SUPPLY BODY PNL SEALANT	New	80.00	0.00
11	REMOVE & INSTALL ENGINE ASSY TO FACILITATE REPAIR (Supplementary)	New	500.00	500.00
12	REMOVE & INSTALL DASHBOARD ASSY TO FACILITATE REPAIR (Supplementary)	New	500.00	500.00
13	REPLACE MAIN WIRING HARNESS TO FACILITATE REPAIR (Supplementary)	New	500.00	500.00
14	REMOVE LH FRONT SEAT, CENTRE SEATS, AND CARPETS TO FACILITATE REPAIR (Supplementary)	New	300.00	300.00
15	SUPPLY & INSTALL LH FRONT QUARTER GLASS SOLAR FILM - RIKECOOL (Supplementary)	New	80.00	80.00
16	REPLACE POWER CABLE (Supplementary)	New	100.00	100.00
Gross Labour Cost (\$\$)			8,935.00	7,695.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >