

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007376/ARA3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070151363
Claimant Vehicle No :	SJU8808E	Insured Vehicle No :	SMV9346Z
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	6832229783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU8808E		
Make & Model:	MERCEDES-BENZ E250, 2.0 AVG (R18 LED) (A)	Engine No:	27492031349617
Reg. Date:	12/02/2018 (Man. Year: 2017)	Chassis No:	WDD2130452A401041
Colour:	Blue	Odometer:	147496 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/40 R18	Rear Tyre Size:	215/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,634.70	846.30	3,788.40	81.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	530.00	700.00	56.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,864.70	1,376.30	4,488.40	76.53
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	5,864.70	1,100.00	4,764.70	81.24
+ GST 7.00/7.00% (S\$)	410.53	77.00	333.53	81.24
Nett Amount (S\$)	6,275.23	1,177.00	5,098.23	81.24
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,479.00		

INSPECTION

Date of Assignment:	02/07/2021	Kang Car Repairers Pte Ltd (HQ)
Date Inspected:	02/07/2021 Inspected At:	No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Estimated Period of Repair:	2.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,309.00 FL	*- FL
2	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	38.00 FL	*- FL
3	1		*REAR LOWER BUMPER	Deformed	389.00 FL	*389.00 FL
4	1		*REAR BUMPER RH MOULDING CHROME	Cut	410.00 FL	*410.00 FL
5	1		*EXHAUST CHROME COVER RH	Not Necessary	314.00 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Necessary	108.00 FL	*108.00 FL
7	1		*TAIL LAMP -RH	Not Necessary	889.00 FL	*- FL
8	2		*REVERSE SENSORS	Not Necessary	626.00 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
					Sub Total (\$\$)	5,143.00 937.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	508.30 90.70
					Total Parts (\$\$)	4,634.70 846.30

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	(REAR) TO SPRAY PAINTING	New	500.00	200.00
3	TO REMOVE AND REPLACE THE DAMAGED PARTS KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	600.00	250.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
Gross Labour Cost (S\$)			1,230.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >