



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBP 170J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMER (SN)	TO REPAIR SEE LABOUR	1,438.75	-
1	GUIDE PIECE (BUMPER BRACKET RH) (SN)	NOT NECESSARY	42.45	-
1	GUIDE PIECE (BUMPER GUIDE RH) (SN)	NOT NECESSARY	34.70	-
1	BUMPER (REINFORCEMENT) (SN)	NOT NECESSARY	549.77	-
1	ATTACHMENT STRIP (SN)	NOT NECESSARY	65.34	-
1	GUIDE PIECE (BUMPER LH BRACKET) (SN)	NOT NECESSARY	34.70	-
1	GUIDE PIECE (BUMPER LH GUIDE) (SN)	NOT NECESSARY	42.45	-
1	TAILLIGHT RHR OUTER (SN)	CUT	307.50	307.50
1	STONE PROTECTION FOIL (SN)	NECESSARY	33.81	33.81
			2,549.47	341.31
	<u>LABOUR</u>			
	DIAGNOSTIC AND PROGRAMMING.		480.00	480.00
	CHECK SHORT CIRCUIT / HARNESS REPAIR.	NOT NECESSARY	280.00	-
	LABOUR. INCLUSIVE OF THE REPAIR OF COVER FOR BUMPER PRIMER.		3,360.00	1,260.00
	SPRAY PAINTING.		3,200.00	1,600.00
			7,320.00	3,340.00
	GRAND TOTAL		9,869.47	3,681.31
	RECOMMENDED COST OF REPAIRS			3,681.31

Report Ref No. CS/UOI21007379/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.